Submit 1 Copy To Appropriate District Office	State of New Me	exico		Form C-103
District I – (575) 393-6161	Energy, Minerals and Natu	ıral Resources		Revised August 1, 201
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	•
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-10216	£1
<u>District III</u> – (505) 334-6178	1220 South St. Fran	ncis Dr.	5. Indicate Type STATE	e of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM &		6. State Oil & C	
1220 S. St. Francis Dr., Santa Fe, NM	HOBB:	300-	o. State Off & C	Jas Lease No.
87505	<u> </u>			
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAL	S AND REPORTS ON WELLS	A ZUIS		or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICAT	TON FOR REDMITH (FORM C 101) FO	OÙ CHCH	Lou Wortham	
PROPOSALS.)		EIVED	8. Well Number	r: 20
	Well Other REC	F1	0.00010.11	•
2. Name of Operator			9. OGRID Num	nber
Chevron USA, Inc. 3. Address of Operator			4323 10. Pool name o	or Wildcat
6301 Deauville Blvd., Midland, TX	X 79706		Eunice, San Ar	
4. Well Location			Buillet, Suil 711	iaros, south
	AL- No-al III 1 CCO 64 6	Ab - 3374 15		
i	the North line and 660 feet from			
	Range 37E, NMPM, County			
	1. Elevation (Show whether DR, 3378' DF	, RKB, RI, GR, etc.)		
Name and the second second	3378 DF			
10 01 1 4		CNT 41	D . O.1	r Data
12. Check App	propriate Box to Indicate N	ature of Notice,	Report or Othe	r Data
NOTICE OF INTE	ENTION TO:	SUB	SEQUENT RI	EPORT OF
	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
<del>_</del>	CHANGE PLANS	COMMENCE DRI	_	P AND A
<del></del>	MULTIPLE COMPL	CASING/CEMENT	_	
DOWNHOLE COMMINGLE				
_				
OTHER:		OTHER:		LY ABANDON
13. Describe proposed or complete				
	. SEE RULE 19.15.7.14 NMAC	C. For Multiple Con	npletions: Attach	wellbore diagram of
proposed completion or recom	pletion			
	Chevron USA INC abandon	ed this well as fol	lows	
	Chevron OSA INC abandon	ica illis well as for	10W3.	
1. 07/22/19 MI RU equipment.				
2. 07/23/19 Set CIBP @ 3850'.				
3. 07/24/19 Pump 90 sacks cmt @	3850'-2961'. Tag TOC @ 3481	<b>.</b>		
4. 07/25/19 Pump 130 sacks cmt @	9 3481'-2196'. Tag TOC @ 222	5'. Pump 50 bbl ML		s cmt @
1229'-932'. Pump 50	sacks cmt @ 335'-surf. Top off	well. Rig down. P&	A complete.	-
			11 11 6	
I hereby certify that the information abo	ive is true and complete to the bo	est of my knowledge	e and belief.	
<i>D.</i> (1-	_			
SIGNATURE				
Ricky Villanueva				
Well P&A Project M	anager			
Well I de A I Toject W	min2			
E mail address: =:==@al	IONE 422 400 4770			
E-mail address: ryqg@chevron.com PF For State Use Only	IONE432-488-4778		<del></del>	
	-	$\wedge$	Λ	8-111-10
APPROVED BY: /// / // Conditions of Approval (if adv):	TITLE C.	U.	_ <b>//</b> †D	ате <u> <b>8-14-19</b></u>