

Submit 1:Copy To Appropriate District Office	State of New M		Form C-103	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Nat	ural Resources WELL AI	Revised July 18, 2013 PI NO. 30-025-29066	
District II - (575) 748-1283	OIL CONSERVATION	N DIVISION		
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Fra	5. Indicat	te Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460	Santa Fe NM 8		STATE FEE 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	aBS		on a dust bease no.	
SUNDRY NOTICES AND REPORTAL WELLS, 2014		7. Lease 1	Name or Unit Agreement Name	
1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTAGE WELLS 109 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR ILUG BACK OA DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM 101) FOR SUITE PROPOSALS.) 1. Type of Well: Oil Well Gas Well SWD 2. Name of Operator Penroc Oil Corporation		OR SUM STATE L	STATE LAND 76	
1. Type of Well: Oil Well Gas Well SWD		8. Well N	8. Well Number #003	
2. Name of Operator Penroc Oil Corporation		9. OGRII	9. OGRID Number 17213	
3. Address of Operator			10. Pool name or Wildcat	
P.O. Box 2769 Hobbs, NM 88240) 	ANDER	RSON RANCH; WOLFCAMP	
4. Well Location				
Unit LetterI	_:660feet from the	EAST line and	4720feet from the	
SOUTHline Section 02	Township 16S	Range 32E	NMPM LEA County	
Section 02	11. Elevation (Show whether DF		NOTE OF THE PROPERTY OF THE PR	
12 Check Appropriate Box	to Indicate Nature of Notice, J		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
	6.42	seport of Other Data		
	NTENTION TO:		IT REPORT OF:	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ P AND A □			
PULL OR ALTER CASING		CASING/CEMENT JOB		
DOWNHOLE COMMINGLE		O'NONTO/O'EMIZITI GGB		
CLOSED-LOOP SYSTEM]		_	
OTHER:	pleted energtions. (Clearly state all	OTHER:	ent dates including estimated data	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
1. Test anchors 2. RU WSU. NU BOP. Unseat par and TOH w/ tubing.				
2. RU WSU. NU BOP. Unseat page and 10H w/ tubing. 3. RU WL. Run gauge ring to 9850'. Run and set CIBP @9850' w/WL dump 35' class H cement on top of CIBP. WOC 4 hrs.				
4. TIH w/ 2-7/8" tbg, tag plug, come up and circulate hole w/ 10# gelled brine.				
5. TOH, RU wireline, perf 5 1/2" Prod csg 2 squeeze holes @ 6850'.				
6. TIH w/pkr&tbg. Pump 50sxs Class H cmt, 50 in & 50 out. 7. Perf 2 holes @ 4191', Squeeze w/50sxs class C cmt. 50 in & 50 out. Tag plug. — P15 50 SX 2400 Base of Sale				
7. Perf 2 holes @ 406', Squeeze w/50sxs class C cmt. 50 in & 50 out. Tag plug. 7. Perf 2 holes @ 406', Squeeze w/50sxs class C cmt. 50 in & 50 out. Tag plug. 7. Perf 2 holes @ 60', Squeeze w/25sxs class C cmt and cement to surface.				
The state of t				
8. Put 5sxs @ surface. Install dry hole marker. 4"4; L'Tall above ground 9. Cut the well head, RD, cut anchors, clean location, and move out.				
	OCD & surface owners requirements			
• •	•			
P.S. No earthern pit, all fluids will	be contained in steel pit & hauled of	f to approved disposal facility.	e Attached	
		56	A ADDROVAL	
Spud Date:	Rig Release D	ate: condit	ions of Approval	
L		Od.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE OF SIGNATURE	RST THE	Described.	DATE 7.5.18	
SIGNATURE CONTRACTOR	TITLE	President	DATE 70 JULY	
Type or print nameM.Y. Me For State Use Only		mymerch@penrocoil.com P	· –	
APPROVED BY: Xxxx 10 Conditions of Approval (if any):	nthe TITLE Comp	liance Officer A	DATE 8-15-19	





GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.