Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OPER STUTOLAND

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMLC068545

SUNDRY NOTICES AND REPORTS ON WELLS SEP 2 7 2018

abandoned we	6. If Indian, Allottee of	r Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agre 891000303F	7. If Unit or CA/Agreement, Name and/or No. 891000303F	
1. Type of Well			8. Well Name and No. POKER LAKE UN		
❷ Oil Well ☐ Gas Well ☐ Other				10  	
2. Name of Operator Contact: TRACIE J CHERRY BOPCO LP E-Mail: tracle_cherry@xtoenergy.com			9. API Well No. 30-015-32127-0	00-S1	
3a. Address 6401 HOLIDAY HILL RD BLD MIDLAND, TX 79707	G 5 SUITE 200 3b. Ph:	Phone No. (include area code) 432-221-7379	10. Field and Pool or NASH DRAW-D	10. Field and Pool or Exploratory Area NASH DRAW-DELAWARE	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish,	11. County or Parish, State	
Sec 7 T24S R30E SWNE 1980FNL 1980FEL			EDDY COUNT	EDDY COUNTY, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES) TO I	NDICATE NATURE O	F NOTICE, REPORT, OR OTI	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off	
	□ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
Subsequent Report	Casing Repair	■ New Construction	□ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Temporarily Abandon		
	□ Convert to Injection	□ Plug Back	■ Water Disposal		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiplie completion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  BOPCO, LP respectfully submits this sundry notice to report the plugging and abandonment of the referenced well.  07/13/18 - 07/17/18  MIRU, POOH w/rods and pump. ND WH, install BOP, FT/PT 1000/300 psi. TOH w/tbg. RIH w/5-1/2" CIBP to 7300', set. Tag to verify. Spot 40 sx class 'C' on top. WOC  07/18/18  Tag cmt.@ 7155'. Circulate 160 bbls.salt gelled mud, test csg to 500 psi. Spot 25 sx class 'C'.  WOC, Tag plug @ 6906'. Spot 30 sx cmt 4500' - 4210'. WOC  14. I hereby certify that the foregoing is true and correct.					
Comm Name(Printed/Typed) TRACIE J	nitted to AFMSS for processing t	O LP, sent to the Carlsbac by DEBORAH MCKINNEY	d		
		1,0000		<del></del>	
Signature (Electronic Submission) Date			118 COD DEC	000	
	THIS SPACE FOR FI	EDERAL OR STATE	ENGEROSED FOR NEC	לאט ר	
Approved By  Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant the applicant the applicant the applicant the applicant the applicant to conduct the applicant the applica	itable title to those rights in the subject operations thereon.  U.S.C. Section 1212, make it a crime to the subject of the su	Office Office for any person knowingly and	SEP 2 / 2018  OTEKINAL LI  WITH STAND FREED OF FIGH		
may among or adocutally					



## united States Department of the Interior

## **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 B. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

## Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation