	DEPARTMENT OF THE INTERIOR OCD Hobbs						FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM56749					
					6. If Indian, Allottee	6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions or AOBBS OCD					7. If Unit or CA/Agree	7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well Gas Well Gas Well Other: INJECTION			AUG 2 2 2019			8. Well Name and No. TEXACO FEDERAL 02				
2. Name of Operator Contact: DELILAH Fi COG OPERATING LLC E-Mail: dflores2@concho.com			RECEIVED		9. API Well No. 30-025-30943-	9. API Well No. 30-025-30943-00-S2				
3a. Address ONE CONCHO CENTER 600 W ILLINOIS AVENUE MIDLAND, TX 79701-4287			o. (include area code)		10. Field and Pool or SWD	10. Field and Pool or Exploratory Area SWD				
4. Location of Well (Footage, Sec., 7			11. County or Parish,	State						
Sec 14 T19S R33E SWNE 1980FNL 2310FEL 32.661997 N Lat, 103.632783 W Lon				LEA COUNTY, NM						
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTIC	E, REPORT, OR OT	HER DATA				
TYPE OF SUBMISSION	•		TYPE O	F ACTION	1					
□ Notice of Intent	otice of Intent		Deepen 🗖 Produ		uction (Start/Resume)	ction (Start/Resume) 🔲 Water Shut-Off				
Subsequent Report	Alter Casing		raulic Fracturing	—	amation					
	Casing Repair		Construction		•	—				
Final Abandonment Notice	 Change Plans Convert to Injection 		g and Abandon Back	_	emporarily Abandon Vater Disposal					
reverse unit. 06/18/19-07/08/ <u>CIBP @ 11.333</u> ', Tagged cmt Rotary wireline & set <u>5 1/2" C</u> tagged 5 1/2", <u>CIBP @ 13 012</u> @ 13.012_15.855', POH. 07/1 tagged <u>CIBP @ 11.022</u> ', Pum <u>11.022'-10.742</u> ', Spotted 30 s <u>30 sx class H cmt w</u> / 2% CAC <u>6210', Circulated hole w/ MLF</u> <u>6210-5857', Perf d csg @ 485</u>	on top of CIBP set <u>@ 13.</u> (BP @ 13.012'. RD rotary '_Pump'd 60 B <u>BLs of H20</u> 1/19 RU Rotary Wireline, p'd 50 BBLs H20 & broke x class H cmt @ 9206-893 L @ 8000-7720'. WOC. T Pressure tested csg, hel	260'. 07/09/1 wireline. 07/ & broke circ set 5.1/2" Cl. circulation. S 26'. WOC. 07 agged plug (d 600 PSI. S	9 POH w/ tbg co 10/19 RIH w/ tbg ulation. Spotted BP @ <u>11,022'. R</u> potted <u>30 sx cla</u> /12/19 Tagged <u>c</u> 0 7765'. 07/1 <u>5/1</u> potted 35 sx cla	bilars & mi <u>35</u> sx classing 35 sx classing	II. RU Ib, ss H <u>cmt</u> RE WL. R <u>IH &</u> DU @ 45'. Spotted 12" CIBP @ @	CLAMA 1 <u>E_1-17-'</u> 2	TION 20´			
14. I hereby certify that the foregoing in	s true and correct.				iten Ductom	<u></u>				
Com	#Electronic Submission For COG mitted to AFMSS for proce	OPERATING I	I.C. sent to the I	Hobbs						
Name (Printed/Typed) DELILAH FLORES			Title REGUL				a			
Signature (Electronic	Submission)		Date 08/05/2	1	ACCEPTED FOI		1			
	THIS SPACE FO	DR FEDER	L OR STATE	OFFICE	USE AUG - 7	2019				
Approved By			Title		Smekinnus	4/5				
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE]				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any po to any matter w	rson knowingly and ithin its jurisdiction.	l willfully to	make to any department o	r agency of the Un	ited			
(Instructions on page 2)) ** BI M PI								
)()	ised ** BLM REVISED - NMOC		27-19	• RE VIO	-'FUK'RE®		4 8 1			

Additional data for EC transaction #476642 that would not fit on the form

~

1

32. Additional remarks, continued

<u>4900-4597'</u>. WOC. 07/16/19 Tagged plug @ 4633'. Perf d csg @ 3400'. Pressured up on perfs to 1000 PSI. Spotted 30 sx class <u>C cmt w/ 2% CACL</u> @ 3450-3147'. WOC. Tagged plug @ 3126'. Perf d csg @ 1700'. Established an injection rate of 2 BPM @ 800 PSI. Broke circulation up the 8 5/8" w/ 20 BBLS. Squeezed 50 sx class <u>C cmt</u> @ 1700-1475'. WOC <u>07/17/19</u> Tagged plug @ 1483'. Perf d csg @ 552'. Established injection rate of 2-3 BPM @ 0 PSI. Pressure tested <u>13</u> 3/8" csg, <u>held</u> <u>1200</u> PSI. ND BOP. NU well head. Squeezed 170 sx class <u>C cmt</u> @ <u>552'</u> & circulated to surface in 5 1/2" & <u>8</u> 5/8" csg. Rigged down & moved off. 07/23/19 Moved in backhoe and welder, dug out cellar, cut off well head, and Paul Flowers w/ the BLM verified cement to surface. Welded on "Below Ground Dry Hole Marker". Backfilled cellar, cut off deadmen, cleaned location, and moved off.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612