Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Expires:	January	31,
Lease Serial No.		
NMLC070335		

	OTICES AND REPORTS ON WELLS
Do not use this	form for proposals to drill or to re-enter BBS Of
abandoned well.	Use form 3160-3 (APD) for such proposal SPBR

abandoned we	II. Use form 3160-3 (APD)) for such pro	posalOBE	S oc	6. If Indian, Allottee of	or Tribe Name	
SUBMIT IN	ructions on pa	ge 2 SEP 0	4 2019	7. If Unit or CA/Agree	ement, Name and/	or No.	
1. Type of Well Oil Well Gas Well Other			RECE		8. Well Name and No. LOOMIS USA A 01		
Name of Operator SHACKELFORD OIL COMPA	BRADY SHAC elford@sbcgloba	CLEI OILD	*EU	9. API Well No. 30-025-01760-00-S1			
3a. Address 3b. Phone No Ph: 432-68			nclude area code) 9784		10. Field and Pool or Exploratory Area TEAS		
MIDLAND, TX 79701	Fx: 432-684-5	026					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 23 T20S R33E SENW 1980FNL 1980FWL					LEA COUNTY,	NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE	NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	• TYPE OF ACTION						
Notice of Intent	Acidize	□ Deeper	1	☐ Product	ion (Start/Resume)	■ Water Shu	t-Off
	☐ Alter Casing	🗖 Hydrau	ilic Fracturing	☐ Reclam	ation	☐ Well Integ	rity
Subsequent Report	☐ Casing Repair	□ New C	onstruction	☐ Recomp	olete	Other	
☐ Final Abandonment Notice	☐ Change Plans		nd Abandon		arily Abandon		
	☐ Convert to Injection	☐ Plug Back		☐ Water I	Disposal		
testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 7/31/2019 - MOVED IN EQUIPMENT GETTING READY TO PLUG WELL 8/6/2019 - OPENED UP WELL, RIH WITH PACKER SET AT 2300' RIGGED UP CEMENTER MIXED AND PUMPED 120 SXS OF CEMENT LEFT WELL SHUT IN FOR THE NIGHT - WILL BE CHECKING IN THE AM 8/7/2019 - OPENED UP WELL 0 PSI - POOH WITH PACKER AND RIH TAGGED CEMENT AT 2512' - RIGGED UP TO PUMP CEMENT - MIXED AND PUMP 120 SXS FROM 2512' TO 1370' SHOULD COVER SHOE AT 1449' 8/8/2019 OPENED WELL - TAGGED CEMENT AT 1425' LAID DOWN TUBING PERF WELL AT 350' GOT RATE AT 1							
BPM AT 350 PSI - MIXED AN	ID PUMPED 40 SXS OF C	EMENT TO SU	JRFACE		RFC	T.AMAT	ION
8/9/2019 - CUT OFF WELL HEAD AND PUT PLATE ON WELL RECLAMATION DUE 2-8-'20'							
	Electronic Submission #4	FORD OIL COMP ing by DEBORA	ANY, sent to	the Hobbs on 08/23/201	IACCEDTED	FOR RECO	RD
Signature (Electronic S	Submission)	D	Pate 08/23/20	019	AUG 2	26 20 19	
	THIS SPACE FO	R FEDERAL	OR STATE	OFFICE U	SE McKin	nen LIE	
A			rial.		CARLSBAD	FIELD OFFICE	**
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant the applicant to conduct the applicant the app	uitable title to those rights in the	not warrant or subject lease	Title Office			Date	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to ma	ake to any department or	agency of the Uni	ted
(Instructions on page 2)							

** BLM REVISED **

FOR RECORD ONLY MMOCD 9-5-19

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

work was completed as per approved plans.

5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.

- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective:

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan
Environmental Protection Specialist
575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612