

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
**HOBBS OGD**  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised August 1, 2011

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-35005
1. Type of Well: Oil Well    Gas Well    Other		5. Indicate Type of Lease STATE    FEE    X
2. Name of Operator Armstrong Energy Corporation		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 1973, Roswell, NM 88202-1973		7. Lease Name or Unit Agreement Name Boyce 15
4. Well Location Unit Letter <u>A</u> : <u>664</u> feet from the <u>North</u> line and <u>499</u> feet from the <u>East</u> line Section <u>15</u> Township <u>16S</u> Range <u>35E</u> NMPM    County <u>Lea</u>		8. Well Number 002
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GR 3987'		9. OGRID Number 1092
		10. Pool name or Wildcat Townsend Permo, Upper Penn

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A    XX  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**SEE ATTACHED**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kyle Alpers TITLE VP Engineering DATE 8/14/2019

Type or print name Kyle Alpers E-mail address: kelpers@aecnm.com PHONE: 575-625-2222

**For State Use Only**

APPROVED BY: Kerry Forth TITLE Compliance Officer DATE 9-5-19

Conditions of Approval (if any)



Armstrong Energy Corporation  
PO Box 1973  
Roswell, NM 88202  
Phone: 575-625-2222  
Fax: 575-622-2512

**Plugging Report  
Boyce 15 #2  
30-025-35005**

- 7/29/2019 Move in equipment and rig up. Released anchor and installed BOP. Tally OOH with tubing. 326 total jts. Pumped 20 bbls fresh water down the casing and SION.
- 7/30/2019 Set CIBP at 10190'. RIH with tubing and tag CIBP. Circulated MLF and test casing. Casing good to 550#. Spot 25 sx Class H cement on top of CIBP. POOH to 9560' and spot 35 sx Class H cement. POOH to 7952' and spot 35 sx Class H cement. Start OOH with tubing and SION.
- 7/31/2019 Finished POOH with tubing. Removed top spool and exposed 5 1/2" casing. Welded on 5 1/2" pull stub. Pulled 150,000# on casing and could not get the slips to move. Shot 1 perf hole at 4275'. Pumped down the annulus and could not get circulation. Shot another hole at 3775'. Pumped down the annulus and got good communication up the 5 1/2" casing. Cut 5 1/2" casing at 3775'. Casing came free. Removed slip and prepared to lay down casing. SION.
- 8/1/2019 Laid down 86 full joints of 5 1/2" casing and the top and bottom cut offs. Reinstalled wellhead and BOP. RIH with tubing to 4325' and circulated wellbore until balance was obtained. Spotted 25 sx cement across the 8 5/8" shoe and POOH. SION
- 8/2/2019 Tagged cement at 4147'. POOH to 3825' and spotted 40 sx cement with CaCl. WOC and tagged cement at 3649'. POOH to 2943' and spotted 40 sx cement across the base of the salt. POOH to 1940' and spotted 40 sx across the top of the salt. POOH to 532' and circulated cement to surface. Took 175 sx. Removed BOP and released it. SION.
- 8/5/2019 Rigged down. Dug out wellhead and cut off. Filled up 9 5/8" casing with 10 sx cement. Installed marker, cut off anchors, cleaned the pit and cleared location.



Paul Kautz  
Hobbs District Geologist  
District I, OCD of NM  
1625 N. French Drive  
Hobbs, NM 88240

August 15, 2019

Good Morning Paul,

Attached is form C-103-Sub Report to final P&A on the following well to be filed in your office:

Boyce 15-2  
API # 30-025-35005

Please let me know if you need anything further.

If you have questions, please feel free to contact me or Kyle Alpers at [kalpers@aecnrm.com](mailto:kalpers@aecnrm.com).

Thank you,

**Shelby Dutton**  
Revenue Accountant  
Production Analyst  
Regulatory

Armstrong Energy Corporation  
PO Box 1973  
Roswell, NM 88202-1973  
Direct Line 575-623-2999 Ext. 309  
Fax 575-622-2512  
[sdutton@aecnrm.com](mailto:sdutton@aecnrm.com)