Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
		Revised July 18, 2013 WELL API NO.		
District I – (575) 393-6161 Energy, Winerais and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1220 South St. Francis Dr.			30-025-06361	
811 S. First St., Artesia, NM 88210			5. Indicate Type of Lease	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 NOV 4 2019 1220 South St. Francis Dr. Santa Fe, NM 87505			STATE TEE	
District IV – (505) 476-3460 Santa Fe, NM 87505			6. State Oil & Gas Lease 1	
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505			B-1732	
87505 SUNDRY NOTICES AND REPORTS ON WELLS				Nama
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Northeast Drinkard Unit (NEDU)	
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well X Gas Well Other			9. OGRID Number	
2. Name of Operator Apache Corporation			873	
3. Address of Operator			10. Pool name or Wildcat	
·				
303 Veterans Airpark Lane, Ste. 3000, Midland, TX 79705 4. Well Location			Eunice;B-T-D, North (22900)	
Unit Letter J :		line and		
Section 2 Township 21S Range 37E NMPM County Lea				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3492' GL				
The state of the s	J-192 GE			
12 Ch l- A		-4 CNI-4.	D O4b D - 4 -	•
12. Check Ap	propriate Box to Indicate N	ature of Notice,	Report or Other Data	15m.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				
			ILLING OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN			=	PNR
DOWNHOLE COMMINGLE				11010
CLOSED-LOOP SYSTEM				
OTHER: OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
1. 10/24/19 Notified OCD of intent. mIRU. 10/25/19 RIH a Tage 5658. Circ MLE.				
2. 10/25/19 Spot 60 sx class "c" cmt @ 5658' w/disp @ 5300'. Calc TOC @ 5300'. Perforate @ 2954'. Squeeze 80 sx class				
"c" cmt w/disp @ 2700'. Tag TOC @ 2656'.				
3. 10/28/19 Perforate @ 1470'. Squeeze 75 sx class "c" cmt w/disp @ 1370'. Tag TOC @ 1315'. Perforate @ 288'. Pump				
surface. Fill up well via 7" csg and circulate cmt on 10 3/4" and 16" csg thru perf @ 288' w/200 sx class "c" cmt. R I mo				
Dig out wellhead & anchors. Cut & remove. Install dry hole marker. Back drag location. P&A complete.				
J	•			
Spud Date:	Rig Release Da	te:	1	
L				
				<u>, </u>
I hereby certify that the information about	ove is true and complete to the bo	est of my knowledg	e and belief.	
\bigcirc	,			
	1/			
SIGNATURE C	7TITLE	Agent	DATE	10/29/2019
<i>V</i>	alou B :: . ·	oupoobuolloos de	so@vahaa sam errarin 40	22 561-9600
Type or print name Jimmy Bagley E-mail address: sunsetwellservice@yahoo.com PHONE; 432-561-8600				
For State Use Only		,	1	
APPROVED BY:	Fite TITLE C. C	$\rho_{\perp} = H$	t DATE	1-7-19
Conditions of Approval (if any):	JUNCE TILLE C.		DAIE / !	
Conditions of Approval (if any): J AUTHERIZED BY Sum BULLS, SR RECLAMATION FOREMAN, APACHE CORPORATION				