District I State of Energy Minerals		t New Mexico s and Natural Resources	Form C-129
District II 811 S. First St., Artesia, NM 88210 Qil Conse		rvation Division OCD	Revised August 1, 2011
District III 1220 Sou 1000 Rio Brazos Road, Aztec, NM 87410 Santa I		ervation Division OCD th St. Francis Dr. Fe, NM 87505	t one copy to appropriate District Office
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		DAFO Permit No.	(For Division Use Only)
APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12 (See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)			
Α.	Applicant EOG Resources ,		
	whose address is PO Box 2267, Midland, Texas 79702,		
	hereby requests an exception to Rule 19.15.18.12 for 90days or until		
	JAN 1 - APR 1 , Yr 2020, for the following described tank battery (or LACT):		
	Name of Lease <u>ATOKA/HEARTTHROB FL</u> Name of Pool <u>96674- TRIPLEX, BONESPRING WEST</u>		
	Location of Battery: Unit Letter B	Section <u>17</u> Township <u>24S</u> Rang	ze <u>33E</u>
	Number of wells producing into battery4		
В.	Based upon oil production of	barrels per day, the estimate	d * volume
	of gas to be flared is EST 110	MCF; Value	per day.
С.	Name and location of nearest gas gathering facility:		
	ATOKA HEARTTHROB FL 90187006		
D.	DistanceEstimated cost of connection		
E.	This exception is requested for the following reasons: <u>All gas will be metered and recorded prior to Flaring</u> .		
	HEARTTHROB BSX STATE 01H 3002541056		
	HEARTTHROB BSX STATE 02H 3002541057 ATOKA BANK BDJ STATE COM 02H 3002541055 ATOKA BANK BDJ STATE COM 03H 3002541058		
OPERATOR		OIL CONSERVATION DIVISION	
I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.		Approved Until 04/01/2	2020
Signature	Kutyen	By	
Printed Name	-		
& TitleKristina Agee - Sr. Regulatory Administrator		Title	
E-mail Address_kristina_agee@eogresources.com		Date 12/31/19	
Date 12/23/2019 Telephone No. 432-686-6996			
 Gas-Oil ratio test may be required to verify estimated gas volume. 			