Submit i Copy To Appropriate District Office	State of New Me	xico	Form C-103	
D1 - 1 - 1 - (600) 200 (16)	Energy, Minerals and Natural Resources		WELL API NO.	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		DIVIGION	30-025-12124	
811 S. First St., Artesia, NM 88210 District III = (505) 334-6178		cis Dr	Indicate Type of Leas	
District II – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 7410 District IV – (505) 476-3460 1220 South St. Francis Dr. Santa Fe, NM 87505		505	STATE 6. State Oil & Gas Lease	FEE X
District IV — (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NMJAN 187505	8 2020 Santa 1 6, 1411 67		6. State Off & Gas Leas	e No.
SUNDRY NOTICE AND ALPORTS ON WELLS			7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PICE 15 TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Edith Butler A	
1. Type of Well: Oil Well X Gas Well Other			8. Well Number	
2. Name of Operator Apache Corporation			9. OGRID Number 873	
3. Address of Operator			10. Pool name or Wildcat	
303 Veterans Airpark Lane, Ste. 3000, Midland, TX 79705			Bline O&G (6660)/Paddock(49210)	
4. Well Location				
	1980 feet from the S		660 feet from the	line
Section 18 Township 22S Range 38E NMPM County Lea				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3336' GL				
				r - ~
12. Check App	ropriate Box to Indicate Na	ature of Notice, R	eport or Other Data	16m
NOTICE OF INTENTION TO: SUB			EQUENT REPOR	T OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				RING CASING
TEMPORARILY ABANDON				\mathcal{D}^{A}
DOWNHOLE COMMINGLE				POR
CLOSED-LOOP SYSTEM				
OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
1. 01/07/20 Notified OCD of intent. Mエレル・ ししま 入工H 十丸 9 @ 50 76' Circ・/20665 MLF。 2. 01/08/20 Spot 25 sx class "c" cmt @ 5076' w/disp @ 4826'. Calc TOC @ 4826'. Spot 45 sx class "c" cmt @ 2850'				
2. 01/06/20 Spot 25 sx class c clift @ 50/6 widisp @ 4626. Calc 100 @ 4626. Spot 45 sx class c clift @ 2650 widisp @ 2419'. Tag TOC @ 2394'.0 n 1 0 a (3-0 .				
3. 01/09/20 Perforate @ 1339'. Squeeze 50 sx class "c" cmt @ 1339' w/disp @ 1239'. Tag TOC @ 1213'. Perforate				
@ 360'. Pump surface via 5 1/2" csg thru perf @ 360' and circulate cmt to surface on 8 5/8" csg w/100 sx				
class "c" cmt. Dig out wellhead & anchors. Cut & remove. Install dry hole marker. Back drag location.				
P&A complete. \ \mathcal{LD} m_\varphi .				
Spud Date:	Rig Release Da	te:		
		<u></u>		
I hereby certify that the information abo	ve is true and complete to the be	st of my knowledge a	and belief.	
\sim	111			
SIGNATURE /	TITLE	Agent	DATE	01/10/20
Type or print name Jimmy Bagi	ev E mail address	. sunsatwallsarvica	@vahoo com DUONE.	432-561-8600
Type or print name				
	1 L /	$_{2}$		1.2020
APPROVED BY: ////	TITLE (DATE/	- 27- 00
APPROVED BY: New Part TITLE () DATE 1-24-20 Conditions of Approval (if any): HUTHORITED 184 DULIN BUNGO, SR. RUCLAMATION FOREMAN, APACHE CORPORATION				
THE INTERIOR OF YOUR SOURCE, OR RECLAMATION POREMAN, HAPPORE CORPORATION				