

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-work an abandoned well. Use form 3160-3 (APD) for such proposals.

HOBBS OCD

SUBMIT IN TRIPLICATE - Other instructions on page 2 **SEP 01 2020**

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well Name and No. FOX FEDERAL 07	
2. Name of Operator LEGACY RESERVES OPERATING LP-Mail: mreyes@legacyreserves.com		9. API Well No. 30-025-36455-00-S1	
3a. Address 303 W WALL SUITE 1600 MIDLAND, TX 79702	3b. Phone No. (include area code) Ph: 432-221-6358	10. Field and Pool or Exploratory Area MALJAMAR	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 31 T17S R32E SWNE 2310FNL 2210FEL		11. County or Parish, State LEA COUNTY, NM	

RECEIVED

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

We are requesting the subject well be placed in TA status for one year due to the current situation the oil industry is in.

08/07/20-Ran MIT, pressured casing to 490#. BLM notified and witnessed by Katherine Jess. Chart is attached.

14. I hereby certify that the foregoing is true and correct. Electronic Submission #526693 verified by the BLM Well Information System For LEGACY RESERVES OPERATING LP, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 08/21/2020 (20PP2812SE)		TA until 8/25/21	
Name (Printed/Typed) MELANIE REYES	Title COMPLIANCE COORDINATOR		
Signature (Electronic Submission)	Date 08/20/2020		

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By ACCEPTED	JONATHON SHEPARD Title PETROELUM ENGINEER	Date 08/25/2020
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office Hobbs

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

FOR RECORD ONLY

Revisions to Operator-Submitted EC Data for Sundry Notice #526693

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	TA SR	TA SR
Lease:	NMLC029410B	NMLC029410B
Agreement:		
Operator:	LEGACY RESERVES OPERATING LP 303 WEST WALL SUITE 1800 MIDLAND, TX 79701 Ph: 432-689-5200	LEGACY RESERVES OPERATING LP 303 W WALL SUITE 1600 MIDLAND, TX 79702 Ph: 432-682-2516 Fx: 432.686. 8318
Admin Contact:	MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com Ph: 432-221-6358	MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com Ph: 432-221-6358
Tech Contact:	MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com Ph: 432-221-6358	MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com Ph: 432-221-6358
Location:		
State:	NM	NM
County:	LEA COUNTY	LEA
Field/Pool:	MALJAMAR	MALJAMAR
Well/Facility:	FOX FEDERAL 07 Sec 31 T17S R32E SWNE 2310FNL 2210FEL	FOX FEDERAL 07 Sec 31 T17S R32E SWNE 2310FNL 2210FEL

BUREAU OF LAND MANAGEMENT

**Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

Conditions of Approval for Temporary Abandonment of Wells

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.

Melanie Reyes

From: jshepard@blm.gov
Sent: Tuesday, August 25, 2020 11:05 PM
To: Melanie Reyes
Subject: Well FOX FEDERAL 07
Attachments: TA COA.docx; EC526693.pdf

HOBBS

SEP 01

RECEIVED

The sundry for Temporary Abandonment you submitted has been accepted by the BLM. Your original Electronic Commerce (EC) transmission was assigned ID 526693. Please be sure to open and save all attachments to this message, since they contain important information.

TA till 08/25/2021

HOBBS OCD
SEP 01 2020
RECEIVED

