

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-20164
5. Indicate Type of Lease <i>Gradent</i> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Cato San Andres
8. Well Number 11
9. OGRID Number 183718
10. Pool name or Wildcat Cato San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
UHC New Mexico Corp.

3. Address of Operator
P.O. Box 450, 303 W. Main, Ste. 300, Artesia, N.M. 88210

4. Well Location

Unit Letter B : 660 feet from the North line and 1980 feet from the East line
Section 8 Township 8S Range 30E NMPM Chavez County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOBS ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

04-19-06 MIRU. Put wellhead & BOP on. RIH w/ bailer & tbg. Clean out to TD @ 3510'. POOH w/ tbg. Closed well & shut down.

04-20-06 RIH w/ packer & tbg to 3000', set packer. Load hole, pressure up to 300psi. Found hole in top ft @ surface. Unset packer, POOH w/ tbg, rig up wireline. Log well, shut down.

04-21-06 RIH w/ production string. Nipple down BOP, flanged well, shut down.

04-24-06 RIH w/ pump & rods, tag, load hole. Spaced out, hang on, check p/a. Nipple up flowline & rig down.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Regina Wolf TITLE Production Clerk DATE 5-23-06

Type or print name Regina Wolf E-mail address: regina@lothian.us Telephone No. 505-746-4448
For State Use Only

APPROVED BY: Gary W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER
Conditions of Approval (if any):

MAY 30 2006