Submit 3 Copies To Appropriate District Office	State of New Mex	xico	Form C-103
District I	Energy, Minerals and Natur	ral Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		-	WELL API NO. 30-025-20519
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIAISION -	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran	cis Dr.	STATE S FEE
District IV	Santa Fe, NM 87	505	5. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	CES AND REPORTS ON WELLS	•	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		D OLIOTT	_
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		<u> </u>	MONSANTO STATE
	Gas Well 🔲 Other	1	8. Well Number
2. Name of Operator			5 9. OGRID Number
POGO PRODUCING COMPANY			017891
3. Address of Operator			10. Pool name or Wildcat
P. O. BOX 10340, MIDLAND, TX	79702-7340]	PADUCA DELAWARE
4. Well Location			
Unit Letter <u>J</u> :_	1650 feet from the SOUTH	line and <u>16</u>	feet from the <u>EAST</u> line
Section 16	Township 25S	Range 32E	NMPM LEA County
《数学》 《数学》	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application O	3420' GR		
	***	nter mell Distan	and from the contract of the c
	terDistance from nearest fresh w		
Pit Liner Thickness: mil	Below-Grade Tank: Volume		truction Material
12. Check A	appropriate Box to Indicate N	ature of Notice, R	eport or Other Data
NOTICE OF IN	TENTION TO	SUBS	EQUENT REPORT OF:
		l .	<u> </u>
PERFORM REMEDIAL WORK □	PLUG AND ABANDON 🔲	REMEDIAL WORK	☐ ALTERING CASING ☐
· · · · · · · · · · · · · · · · · · ·	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILL	_
PERFORM REMEDIAL WORK		l .	LING OPNS. P AND A
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS	COMMENCE DRILL CASING/CEMENT	LING OPNS. P AND A DOB DOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: RETURN WELL TO F	CHANGE PLANS	COMMENCE DRILL	LING OPNS. P AND A
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: RETURN WELL TO F	CHANGE PLANS MULTIPLE COMPL PRODUCTION letted operations. (Clearly state all p	COMMENCE DRILL CASING/CEMENT OTHER:	JOB P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: RETURN WELL TO F	CHANGE PLANS MULTIPLE COMPL PRODUCTION letted operations. (Clearly state all p	COMMENCE DRILL CASING/CEMENT OTHER:	LING OPNS. P AND A DOB D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: RETURN WELL TO F	CHANGE PLANS MULTIPLE COMPL PRODUCTION letted operations. (Clearly state all p	COMMENCE DRILL CASING/CEMENT OTHER:	JOB P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: RETURN WELL TO FEMALE. 13. Describe proposed or composed of starting any proposed work.	CHANGE PLANS MULTIPLE COMPL PRODUCTION letted operations. (Clearly state all p	COMMENCE DRILL CASING/CEMENT OTHER:	JOB P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: RETURN WELL TO FEMALE. 13. Describe proposed or compof starting any proposed woor recompletion.	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all process) rk). SEE RULE 1103. For Multiple	COMMENCE DRILL CASING/CEMENT OTHER: Detrinent details, and gle Completions: Attach	ING OPNS P AND A DOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: RETURN WELL TO FEMALE. 13. Describe proposed or composed of starting any proposed work.	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all process) rk). SEE RULE 1103. For Multiple	COMMENCE DRILL CASING/CEMENT OTHER: Detrinent details, and gle Completions: Attach	ING OPNS P AND A DOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: RETURN WELL TO FEMALE. 13. Describe proposed or compof starting any proposed woor recompletion. AFE has been generated to repair or	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all process) rk). SEE RULE 1103. For Multiple	COMMENCE DRILL CASING/CEMENT OTHER: Detrinent details, and gle Completions: Attach	ING OPNS P AND A DOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: RETURN WELL TO FEMALE. 13. Describe proposed or compof starting any proposed woor recompletion. AFE has been generated to repair or	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all process) rk). SEE RULE 1103. For Multiple	COMMENCE DRILL CASING/CEMENT OTHER: Detrinent details, and gle Completions: Attach	ING OPNS P AND A DOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: RETURN WELL TO FEMALE. 13. Describe proposed or compof starting any proposed woor recompletion. AFE has been generated to repair or	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all process) rk). SEE RULE 1103. For Multiple	COMMENCE DRILL CASING/CEMENT OTHER: Detrinent details, and gle Completions: Attach	ING OPNS P AND A DOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: RETURN WELL TO FEMALE. 13. Describe proposed or compof starting any proposed woor recompletion. AFE has been generated to repair or	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all process) rk). SEE RULE 1103. For Multiple	COMMENCE DRILL CASING/CEMENT OTHER: Detrinent details, and gle Completions: Attach	ING OPNS P AND A DOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: RETURN WELL TO FEMALE. 13. Describe proposed or compof starting any proposed woor recompletion. AFE has been generated to repair or	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all process) rk). SEE RULE 1103. For Multiple	COMMENCE DRILL CASING/CEMENT OTHER: Detrinent details, and gle Completions: Attach	ZING OPNS. P AND A JOB give pertinent dates, including estimated date ch wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING TOTHER: RETURN WELL TO FEMALE. 13. Describe proposed or compof starting any proposed woor recompletion. AFE has been generated to repair or well service unit in the near future.	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all prk). SEE RULE 1103. For Multiple replace the casing, frac the Ramsey	COMMENCE DRILL CASING/CEMENT OTHER: Description of the Completions: Attack formation and return the completion of the Co	ING OPNS. PAND A DOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING TOTHER: RETURN WELL TO FEMALE. 13. Describe proposed or compof starting any proposed woor recompletion. AFE has been generated to repair or well service unit in the near future.	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all prk). SEE RULE 1103. For Multiple replace the casing, frac the Ramsey	COMMENCE DRILL CASING/CEMENT OTHER: Description of the Completions: Attack formation and return the completion of the Co	ING OPNS P AND A DOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING THE TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all prk). SEE RULE 1103. For Multiple replace the casing, frac the Ramsey above is true and complete to the beclosed according to NMOCD guidelines	COMMENCE DRILL CASING/CEMENT. OTHER: Description and general permit	and belief. Further certify that any pit or below-
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING TOTHER: RETURN WELL TO FEMALE. 13. Describe proposed or compof starting any proposed woor recompletion. AFE has been generated to repair or well service unit in the near future.	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all prk). SEE RULE 1103. For Multiple replace the casing, frac the Ramsey	COMMENCE DRILL CASING/CEMENT OTHER: Description of the Completions: Attack formation and return the completion of the Co	ING OPNS. PAND A DOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING THE TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all prk). SEE RULE 1103. For Multiple replace the casing, frac the Ramsey above is true and complete to the beclosed according to NMOCD guidelines [COMMENCE DRILL CASING/CEMENT. OTHER: Description and general permit control of the completion of the	give pertinent dates, including estimated date ch wellbore diagram of proposed completion the well to production? Page will MIRU and belief. I tarther certify that any pit or belower an (attached) atternative OCD-approved plan DATE 05/23/06
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING THE TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all prk). SEE RULE 1103. For Multiple replace the casing, frac the Ramsey above is true and complete to the beclosed according to NMOCD guidelines [COMMENCE DRILL CASING/CEMENT. OTHER: Description and general permit control of the completion of the	give pertinent dates, including estimated date ch wellbore diagram of proposed completion the well to production? Page will MIRU and belief. I tarther certify that any pit or belower an (attached) atternative OCD-approved plan DATE 05/23/06
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THE RETURN WELL TO FE TO STATE THE TOTAL STATE TO THE TEMPORARILY ABANDON THE RETURN WELL TO FE TO THE TEMPORARILY ABANDON TO THE TEMPORARILY ABAND	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all prk). SEE RULE 1103. For Multiple replace the casing, frac the Ramsey above is true and complete to the beclosed according to NMOCD guidelines TITLE IGHT E-mail address: wrighted	COMMENCE DRILL CASING/CEMENT. OTHER: Description and general permit control of the completion of the	And belief. Tarther certify that any pit or below- ran (attached) attersative OCD approved plan DATE 05/23/06 Telephone No. 432-685-8100
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING TOTHER: RETURN WELL TO FEMALE TO SEMALE TO SEMALE TO THE TEMPORARILY ABANDON TO THE TEMPORARI	CHANGE PLANS MULTIPLE COMPL PRODUCTION leted operations. (Clearly state all prk). SEE RULE 1103. For Multiple replace the casing, frac the Ramsey above is true and complete to the beclosed according to NMOCD guidelines [COMMENCE DRILL CASING/CEMENT. OTHER: Description and general permit control of the completion of the	and belief. Further certify that are put or belowant (attached) alternative OCD approved plan DATE 05/23/06 Telephone No. 432-685-8100

estatification of

Submit 3 Copies To Appropriate District