## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION WELL API NO. 1220 South St. Francis Dr. **DISTRICT I** 1625 N. French Dr., Hobbs, NM 88240 32-025-28308 Santa Fe, NM 87505 5! Indicate Type of Lease STATE FEE 1 1301 W. Grand Ave, Artesia, NM 88210 6. State Oil & Gas Lease No. **DISTRICT III** 1000 Rio Brazos Rd, Aztec, NM 87410 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A South Hobbs (G/SA) Unit Coop DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) Section 34 8. Well No. 1. Type of Well: Oil Well Gas Well Other Injection 9. OGRID No. 157984 2. Name of Operator Occidental Permian Ltd. 10. Pool name or Wildcat Hobbs (G/SA) 3. Address of Operator HCR 1 Box 90 Denver City, TX 79323 4. Well Location Feet From The Unit Letter L 1980 Feet From The South West County 18-S 38-E Township Section 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3636' KB Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well \_\_\_\_\_\_ Distance from nearest surface water Pit Type Depth of Ground Water Below-Grade Tank: Volume \_\_ bbls; Construction Material Pit Liner Thickness Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PLUG & ABANDONMENT **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB **PULL OR ALTER CASING Multiple Completion** OTHER: Open Additional Perfs/Stimulate Х OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well. Pull injection equipment. 2. CO well to PBTD @4457'. 3. Perforate 4224-32, 4286-90, 4408-13 w/4" select fire gun @4 JSPF 4. Acidize perfs 4173-4440' with 15% HCL acid. 5. Circulate well clean. 6. Run back in hole w/injection equipment. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or or an (attached) alternative OCD-approved closed according to NMOCD guidelines , a general permit plan SIGNATURE TITLE Administrative Associate DATE 05/24/2006 TELEPHONE NO. TYPE OR PRINT NAME 806-592-6280 ohnson E-mail address: Mendy johnson@oxy.com For State Use Only APPROVED BY CONDITIONS OF APPROVAL IF AD