Sumait 3 copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

District Office	znorgy, minorals and matarar no	ood. coo Boparanom	Revised 1-	-1-89
<u>DISTRICT I</u>	OIL CONSERVATION	ON DIVISION	WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		30-025-06940	
DISTRICT II	Santa Fe, New Mexico		5. Indicate Type of Lease	
P.O. Box Drawer DD, Artesia, NM 88210 DISTRICT III	,		STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410		,	6. State Oil / Gas Lease No.	
	TICES AND REPORTS ON WELL	S	Control of the Contro	
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESE		N OR PLUG BACK TO	7. Lease Name or Unit Agreement Name W.T. MCCOMACK	West of the Re
1. Type of Well: OIL GAS WELL WELL				
Name of Operator CHEVRON USA INC			8. Well No. 11	
Address of Operator			Pool Name or Wildcat MCCORMACK SILURIAN	
4. Well Location				
Unit Letter A:	554' Feet From The NORT	H Line and 554'	_Feet From The <u>EAST</u> Line	
Section 32	Township 21-S R	ange <u>37-E</u> NM	IPMLEA_ COUNTY	
	10. Elevation (Show whether DF, RKB,	RT,GR, etc.) 3473' GL		
11. Check A	ppropriate Box to Indicate Nati	ure of Notice, Report,	or Other Data	
NOTICE OF INTENTION	ON TO:	SU	JBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPE	ERATION PLUG AND ABANDONMENT	П
PULL OR ALTER CASING		CASING TEST AND CEMEN		
OTHER:		OTHER:	SILURIAN COMPLETION	V
4-10-06: MIRU. 4-11-06: LD PUMP & RODS. REL TAC. LD 180 JTS 2 7/8" TBG, TAC, 14 JTS, SN OPEN ENDED. 4-12-06: PMP KILL FLUID DN TBG. TIH W/BIT TO 6558'. TIH W/2 7/8" WS W/PKR TO 5371, 172 JTS. SET PKR. LOAD & TEST CSG TO 500#. 4-13-06: TIH W/PKR TO 5957. DID NOT HOLD. TIH W/PKR TO 6102. DID NOT HOLD. TIH W/PKR TO 6174. SET PKR. HELD. SET BLOW DOWN TANK. 4-14-06: CIRC W/FOAM UNIT. TIH W/MILL DN TO 6558. MILL TO 6594. POOH TO 5356. 4-17-06: TAG @ 6584. CLEAN OUT WELL. WASH 6584-6647'. 4-18-06: TAG @ 6642. TIH W/HD COMPRESSION PKR W/S, 198 JTS TO 6173. SET PKR. LD 26 JTS TO 5371, 172 JTS. SET PKR. 4-19-06: SQZ PERFS 5585-5900 & HOLE IN CSG @ 6134-47 W/351 SX CL H, FOLLOWED BY 150 SX. REVERSE OUT 800' CMT OUT OF TBG. TOH W/PKR TO 4921. REV OUT 45 BBLS. SET PKR. 4-20-06: REL PKR. TIH W/BIT & TAG @ 5365. DRILL 5365-5535. 4-24-06: TIH W/BIT TO 5516, 5920, 186 JTS. NO FILL. DRILL 5920-6150. FELL THRU. TIH W/WS TO 6227, 196 JTS. WASH DN 6227-6645 TO 6650. DRILL ON CIBP. 4-25-06: TIH FROM 5890-6650'. DRILL CIBP LOST CIRC. PUMP 100 BBLS. WELL ON VAC. TIH W/BIT, CHASING CIBP TO 7165. DRILL TAKING FLUID. 4-26-06: CIRC W/FOAM UNIT. WOULD NOT CIRC. 4-27-06: TIH W/BIT TO 7086, CIBP, 244 JTS. DRILL ON CIBP. DRILL 1 FOOT. CHASE DN 29' TO 7115. DRILL 715-7120. 4-28-06: DRILL 7120-7121. FELL DN TO 7135. DRILL TO 7143. RETURNS ALL CIBP. POOH TO 5890. 5-01-06: TIH W/BIT TO 7085. DRILL 30 MINUTES. FELL THRU 2 JTS TO 7135. DRILL 7135-7143. 5-02-06: TIH W/BIT TO 7085. DRILL 30 MINUTES. FELL THRU 2 JTS TO 7135. DRILL 7135-7143. 5-02-06: TIH W/BIT TO 7085. DRILL 30 MINUTES. FELL THRU 2 JTS TO 7135. DRILL 7135-7143. 5-02-06: TIH W/BIT TO 7085. DRILL 30 MINUTES. FELL THRU 2 JTS TO 7135. DRILL 7135-7143. 5-02-06: TIH W/BIT TO 7085. DRILL 30 MINUTES. FELL THRU 2 JTS TO 7135. DRILL 7135-7143. 5-02-06: TIH W/BIT TO 7085. DRILL 30 MINUTES. FELL THRU 2 JTS TO 7135. DRILL 7135-7143. 5-02-06: TIH W/BIT TO 7085. DRILL 30 MINUTES. FELL THRU 2 JTS TO 7135. DRILL 7135-7143. 5-02-06: TIH W/BIT TO 7085. DRILL 30 MINUTES. FELL THRU 2 JTS TO 7135. DRILL 71				
Ω	.,			
I hereby certify that the information above is true and complete SIGNATURE	1 / 1/07 - 504 \	ılatory Specialist	DATE	
TYPE OR PRINT NAME D	enise Pinkerton		Telephone No. 432-687-73	375
(This space for State Use) APPROVED CONDITIONS OF ARPROVAL, IF AN	TITLE PETHOLIC	EUM ENGINEER O()	DATE MAY 3 1 2006 DeSoto/Nichols 12-93 ver 1.0	