

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-09199
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 26711
7. Lease Name or Unit Agreement Name King "C"
8. Well Number 1
9. OGRID Number 002799
10. Pool name or Wildcat Jalmat Tansill YT 7 Rivers

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Steel Depth to Groundwater 300' Distance from nearest fresh water well >1000' Distance from nearest surface water >1000'

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator  
Breck Operating Corp.

3. Address of Operator  
P.O. Box 911, Breckenridge, Texas 7624

4. Well Location  
Unit Letter G : 2117 feet from the North line and 1980 feet from the East line  
Section 1 Township 23S Range 36E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3416' DF

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

03-24-06 Called OCD. MIRU P&A equipment. ND WH. NU BOP. PU & start RIH w/7" CIBP & tbg. DSEWE.

03-27-06 OCD rep on location. Finish TIH. Set CIBP @ 2488'. Circ mud. Mix & pump plug #1 (25 sxs). POOH. RU WL. Perf csg @ 1437'. POOH. RD WL. TIH w/pkr & tbg. Pressure up on csg. Circ out bradenhead. Notify OCD. Mix & pump plug #2 (25 sxs). Shut-in 250# tbg pressure. WOC.

03-28-06 TIH w/tbg. Tag @ 1429'. Called OCD. Mix & pump plug #3 (25 sxs). POH & WOC. RU WL. TIH & tag @ 1280'. OCD on location. RD WL. TIH to 300'. Mix & pump plug #4 (25 sxs). POH to 60'. Mix & pump plug #5 to surface. Dig out, cut off WH. Well P&A'd.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Ernie Underwood TITLE District Engineer DATE June 2, 2006

Type or print name Ernie Underwood E-mail address: eunderwood@breckop.com Telephone No. 254-559-3355 ext 238  
**For State Use Only**

APPROVED BY: Hay W. Wink TITLE  DATE JUN 06 2006  
Conditions of Approval (if any)

OC FIELD REPRESENTATIVE II/STAFF MANAGER