## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-23481	
DISTRICT II	Santa i e,	1444 07303	5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III			6. State Oil & Gas Lease No.	<del></del>
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NO	TICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agree	ement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Un	it
	APPLICATION FOR PERMIT" (Form C-1	01) for such proposals.)	Section 19	
1. Type of Well:  Oil Well X	Gas Well Other		8. Well No. 242	
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.  3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	C 79323			
4. Well Location				
Unit Letter N : 420	Feet From The South		From The West	Line
Section 19	Township 18-S	Range 38-E	NMPM 151	6 17 18 2 County
	11. Elevation (Show whether DF, RF		188/////	
	3658, GT			<u>/////////////////////////////////////</u>
Pit or Below-grade Tank Application	or Closure	agency freeh water well	1.110	
The Type Deput of Ground water Distance from hearest fresh water wen				
Pit Liner Thickness mil			للآني	John A.
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF 100 100 100 100 100 100 100 100 100 10				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		IG CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI				ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB				
<del></del>			11300	
OTHER: Open Additional Perfs/A	cid Treat X	OTHER:		
<ol> <li>Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> <li>Kill well. POOH w/ESP equipment.</li> <li>Clean out well to CIBP @4220'.</li> <li>Pull CIBP out of hole.</li> <li>Clean out well to CIBP @4350'.</li> <li>Perforate hole w/4" select fire casing guns @2 JSPF at the following depths 4142-52', 4157-67', 4195-4205', 4215-32', 4240-47', 4253-66'.</li> <li>Acid treat new &amp; existing perforations with 15% HCL.</li> <li>Circulate well clean.</li> <li>Scale squeeze well.</li> <li>Run back in hole with ESP equipment.</li> </ol>				
I hereby certify that the information above is constructed or closed according to NMOCD guidelines.  SIGNATURE		or an (attached) alternative plan	Associate DA	TE <u>06/08/2006</u>
TYPE OR PRINT NAME Mendy A	Johnson (E-mail address:	Mendy_johnson@oxy.com	TELEPHONE NO	O. 806-592-6280
For State Use Only	OC BIS	TRICT SUPERVISOR/GET	NERAL MANAGER	
APPROVED BY	Yllen	TITLE		ATE
CONDITIONS OF APPROVAL IF ANY:				JUN 1 5 2006