

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 87240

District II

811 South First, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30 - 025 - 36220

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

V-05343

7. Lease Name or Unit Agreement Name:

State Com 9

8. Well No.

1

9. Pool name or Wildcat

Feather Morrow, North

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

H.L. Brown Operating L.L.C.

OGRID # 213179

3. Address of Operator

300 West Louisiana, Midland, Texas 79702

4. Well Location

Unit Letter **H** : **1650'** feet from the **North** line and **990'** feet from the **East** line

Section **9** Township **15 - S** Range **32 - E** NMPM **Lea** County

1. Elevation (Show whether DR, RKB, RT, GR, etc.)

4303' GL, 4320' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER Temporarily Abandon the **Morrow formation** ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ☐

ABANDONMENT

CASING TEST/ CEMENT JOB ☐

OTHER ☐

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

6-16-03 to 6-25-03: Tested the Morrow from 12,344' to 12,364'.

We wish to temporarily abandon the Morrow interval:

- 1. POH with packer and tubing.**
- 2. Set CIBP at ~ 12,300' and cap with 35' cement.**
- 3. Test casing to 500 psi for 30 minutes.**



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE TITLE **Petroleum Engineer** DATE **6-26-03**

Type or print name **Robert McNaughton** Telephone No. **915 - 688 - 3726**

(This space for State use)

APPROVED BY TITLE **OC FIELD REPRESENTATIVE II/STAFF MANAGER** DATE **JUL 31 2003**

Conditions of approval, if any: