Submit 3 Copies To Appropriate District	State of	New Me	xico	Form C-103		
Office District I	Energy, Minerals and Natural Resources				Revised June 10, 200	3
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.			
District II OH, CONGEDIA TION DIVIGION			30-041-20819		_	
1301 W. Grand Ave., Artesia, NW 66210			<ol><li>Indicate Type</li></ol>		-	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505			STATE	FEE	_	
District IV	Santa F	e, NM 8/	303	6. State Oil & G	as Lease No.	- 1
1220 S. St. Francis Dr., Santa Fe, NM 87505						
	CES AND REPORTS O	N WELLS		7. Lease Name of	or Unit Agreement Name	$\neg$
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				SPEIGHT		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						
PROPOSALS.) 1. Type of Well:				8. Well Number 1		
Oil Well Gas Well	Other					
				0.00010.11	1 100040	4
2. Name of Operator EAGLE RESOURCES,L.P.				9. OGRID Num	ber 182843	
				10 70 1	W'11 / THE	$\dashv$
3. Address of Operator P.O. BOX 3900 ROSWELL,NM 88202-3900				10. Pool name or Wildcat TULE-		
				MONTOYA		
4. Well Location						- 1
TT. 24 T . 44	00 6.464		1:	On fact from	the WEST line	
Unit LetterI:14	00ieet from theS	OUTH	line and12	80ieet irom	theWESTline	ŀ
Section 22	Township 2	) C I	Range 29-E	NMPM 1	ROOSSEVELT County	
					ROOSSEVELT County	
	4388 GL.	neiner DK,	KKD, KI, GK, etc.,			
		. 1!4 - NT	-4	D O41	Dete	
	Appropriate Box to In	ndicate N				
NOTICE OF IN		. —	1	SEQUENT RE		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	<b>1</b> 🗆	REMEDIAL WOR	к 🗆	ALTERING CASING	i
TEMPODADU V ADAMDOM	OLIANOE DI ANO		COMMENCE DO	LLING ODNIG		
TEMPORARILY ABANDON				LLING OPNS.	PLUG AND  ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE		CASING TEST A	ND 🗆	ADAINDONNENT	
. 422 4.7.2.2.1.6.7.66	COMPLETION		CEMENT JOB			
OTHER:			OTHER:			
<ol><li>Describe proposed or comp</li></ol>						
of starting any proposed wo	ork). SEE RULE 1103.	For Multip	le Completions: At	tach wellbore diag	ram of proposed completi	on
or recompletion.					,	
8/02/03 EST.START					Sath Sag	
RETURN MONTOYA INTER		N			and the state of t	
PULL PLUG FROM 'N' NIP		TO IC DEF	TO 5004 00			
PERF 7060-7084 AND 7098-	7130 WITH 4SPF (EXIS	STING PER	CFS 7084-98)	,	.00	
RUN 100 BHP TEST	AND LITERDON			''''	1 5000 34/	
FRAC. 126,000 GAL BRINE AND LITEPROP  RETURN TO PRODUCTION					".;ED	
RETURN TO PRODUCTION	•			h-	unhbs 2	
					0CD	
ATTACHED: WELLBORE I	DIAGRAM				<i>y</i>	
ATTACHED. WELEBOKE	DIAGRAM					
I hereby certify that the information	ahaya is true and sample	ata ta tha h	act of my lenguilada	a and ballaf	·	
r negety certify that the information	above is true and comple	ste to me o	ast of fifty knowledg	e and benen.		
SIGNATURE Juit Calle		TITLE	Sacret		DATE 8/2/103	
Side of the same o	<u> </u>	_*****	y esu		_ Unit of of o	
Type or print name Tim Colli	'e/	E-mail ad	ldress time of e	aglena · mul	DATE <u>8/2//03</u> Celephone No <b>505-1,22.9</b>	800
(This space for State use)				, , , , , , , , , , , , , , , , , , , ,	<u> </u>	
		ר בובו ה ה	EDDECENITATIVE I	STAFF MANAG	ER	_
(Time space for State ase)		C FIELD R	EPRESENTATIVE I	I/STAFF MANAG	<u>E</u> P	
APPPROVED BY Lary U	1,1000	C FIELD R	EPRESENTATIVE I	I/STAFF MANAG	<u>E</u> P	
	1,1000	C FIELD R	EPRESENTATIVE I	I/STAFF MANAG	е <b>°</b> _datr <b>dUL 3 1 2</b> 0	