,	
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resonant	urces Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-025-36246
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.	5. Indicate Type of Lease FEDERAL STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. VA-2742
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:	7. Lease Name or Unit Agreement Name: Goff State
Oil Well Gas Well Other: Dry Hole	·
2. Name of Operator	7. Well No.
SAHARA OPERATING COMPANY	1 O Parl name of Wildow
3. Address of Operator P.O. BOX 4130, Midland, TX 79704	9. Pool name or Wildcat Wildcat
4. Well Location	
	feet from the <u>East</u> line
	33-E NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4257' GL	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED	OIAL WORK ALTERING CASING
TEMPORARILY ABANDON	
PULL OR ALTER CASING MULTIPLE CASING TEST AND MULTIPLE CEMENT JOB	
OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 7-16-93 MIRU United Rig #12. Spudded 12.25 hole @ 6:00 PM. 7-22-03 Drilled to csg point 1650'. Ran 8-5/8", 32#/ft K-55 LT&C csg w/11 centralizers & set @ 1645'. RU BF& cmtd w/600 sx 35:65:6 W/1/4#/sk Celloflake & 2% CaCL2, Tailed w/200 sx Class C w/2% CaCl2. Circulated Science of the completion of recompletion or recompilation.	
. To obtain the control of the contr	
7-29,30-03 Drilled to TD 3625' w/no shows. Ran logs. TIH w/OEDP and set 30 sx plug @ 3625 3508'. Set 60 sx plug @ 1696'-1461'. WOC 4 hrs, TIH tagged plug @ 1496'. Set 30 sx plug @ 404'-287'. ND BOR ttake off WH	
& set 10 sx plug 15' to surf. Install dry hole marker & rel rig. Well P&A.	
e D	
hereby certify that the information above is true and complete to the best of my	knowledge and belief.
SIGNATURE TITLE Preside	ent DATE _7/31/03
Type or print name Robert McAlpine	Telephone No.432-697-0967
(This space for State use)	
APPPROVED BY LOWING DOUBLE REPRESENTATIVE 11/STAFF MANAGER AUG 0 5 2003	
Conditions of approval, if any:	
Approved as to plugging of the Well Born	

Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.