

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-01048
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name MATHERS A
8. Well Number 2
9. OGRID Number 144070
10. Pool name or Wildcat Bagley Permo - Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☒ Other ☐ Injection Well ☐

2. Name of Operator
PALADIN ENERGY CORP

3. Address of Operator
10290 Monroe Drive, Suite 301, Dallas, TX 75229

4. Well Location
Unit Letter **F**: **1980** feet from the **NORTH** line and **1980** feet from the **WEST** line
Section **3** Township **12S** Range **33E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4260' RKB

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type **STEEL** Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-20-06 Set pkr. @7,350'. Sqz. 25 sx. cmt. @7,650'. Tag plug @7,498'. Circulate hole with mud. Spot 25 sx. cmt. @5,600'.
6-21-06 Tag plug @5,340'. Cut 5 1/2" csg. @3,815'.
6-22-06 Spot 35 sx. cmt. @3,865'.
6-23-06 Tag plug @3,698'. Spot 50 sx. cmt. @1,700'. Spot 50 sx. cmt. @350'. Tag plug @156'. Spot 20 sx. cmt. from 60' to surface.
Install Dryhole Marker.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Roger Massey TITLE **AREA MANAGER**

DATE: 6-26-06

Type or print name **ROGER MASSEY**

Telephone No. **432-530-0907**

For State Use Only

APPROVED BY: Hayden Wink TITLE **OC FIELD REPRESENTATIVE II/STAFF MANAGER**

Conditions of Approval (if any):

DATE **JUL 05 2006**