Submit 3 copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office			Neviseu 1-1-03
DISTRICT I	OIL CONSERVA	TION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			30-025-20249
DISTRICT II Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease
P.O. Box Drawer DD, Artesia, NM 88210 DISTRICT III			STATE 🗹 FEE 🗌
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No. B-270
SUNDRY NOTICES AND REPORTS ON WELLS			dentities to the same at the same
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI			7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.			VACUUM GLORIETA WEST UNIT
1. Type of Well: OIL GAS WELL OTHER			
WELL WELL OTHER 2. Name of Operator			8. Well No.
CHEVRON USA INC			46
Address of Operator 15 SMITH RD, MIDLAND, TX 79705			9. Pool Name or Wildcat
4. Well Location VACUUM GLORIETA			
Unit Letter N : 990 Feet From The South Line and 1650 Feet From The West Line			
Section 25 Township 17S Range 34E NMPM Lea COUNTY			
40. Elevation (Chou whather DE, DIVD, DT, CD, etc.)			
GR-4005			
Check Appropriate Box to indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTIO	N TO:	SI	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	ERATION PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEME			NT JOB
OTHER: REQUEST TO TEM	PORARILY ABANDON	OTHER:	
 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. CHEVRON U.S.A. INC. INTENDS TO TEMPORARILY ABANDON THE SUBJECT WELL. THE ISOLATION PACKER ASSEMBLY HAS FAILED, WAS PULLED & RE-RUN THREE TIMES. IT IS RECOMMENDED THAT THE ISOLATION PACKER ASSEMBLY BE PULLED & THE WELL BE TA'D BEFORE THE EQUIPMENT IS SEVERELY DAMAGED. THE INTENDED PROCEDURE IS AS FOLLOWS: 1) MIRU PU. 2) INSTL BOP. 			
1) MIRU PU. 2) INSTL BOP. 3) TOH W/PROD EQPT. 4) TIH W/ON/OFF TOOL & LATCH INTO ON/OFF TOOL ON ISOLATION PACKER ASSEMBLY. 5) TOH W/ISOLATION PACKER SETUP. 6) TIH W/CIBP & SET @ 5700'. 7) LOAD HOLE & CHART TEST FOR NMOCD TA STATUS. THE WELLBORE DIAGRAM IS ATTACHED FOR YOUR APPROVAL.			
I hereby certify that the information above is true and complete SIGNATURE TYPE OR REINIT NAME	noke for title F	Regulatory Specialist	DATE
TYPE OR PRINT NAME DE	enise Pinkerton		<u>.</u>
APPROVED CONDITIONS OF APPROVAL IF ANY:	mb _{TITL} OC FIELD REP	resentative hystaff m	JUL 1 2006 IANAGER JUL 00-1-02066-10

VGWU #46H API No. 30-025-20249

