State of New Mexico

Form C-103

District Office		inergy, Militerals and IN	aturai ive	sources Department			Revised 1-1-89
<u>DISTRICT I</u>	0	IL CONSERV	ATIO	ON DIVISION	WELL API NO.		
P.O. Box 1980, Hobbs, NM	, Hobbs, NM 88240 P.O. Box 2088				30-025-06941		
ISTRICT II Santa Fe, New Mexico 87504-2088					5. Indicate Typ	e of Lease	
P.O. Box brawer DD, Artesia, NW 66210						STATE [FEE 🗹
DISTRICT III 1000 Rio Brazos Rd., Aztec	NIM 87/110				6. State Oil / G	as Lease No.	
		S AND REPORTS C	N WELL	S	alch e		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO						or Unit Agreement Na	ame
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.					CENTRAL DRINKARD UNIT		
1. Type of Well: OIL GAS WELL OTHER							
2. Name of Operator CHEVRON USA INC					8. Well No.	132	
Address of Operator					9. Pool Name o	or Wildcat DRINKARD	
4. Well Location							
Unit Letter	B : 55	54' Feet From The	NORT	H Line and 1874'	_Feet From T	he EAST L	ine
Section 32	То	ownship 21-S	R	ange <u>37E</u> NM	1PM	LEA CC	OUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)							
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
NOTICE OF	INTENTION	TO:		SL	JBSEQUE	NT REPORT C	F:
PERFORM REMEDIAL WOR		JG AND ABANDON		REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON		ANGE PLANS		COMMENCE DRILLING OPE	ERATION 🗆	PLUG AND ABANDO	NMENT
PULL OR ALTER CASING							
OTHER:				OTHER:		PSTOCK & C/O	V
 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 6-20-06: MIRU KEY #235. UNSEAT PUMP. REL TAC. 6-21-06: TIH W/BOX TAP, JARS, BMPR SUB, COLLARS & 2 7/8" WS & TAG WHIPSTOCK @ 6488". LATCH ONTO WHIPSTOCK. 6-22-06: TIH W/TAPER BOX TAP & JARS, BMPR SUB, ON 205 JTS TBG & TAG @ 6498. PUSH WHIPSTOCK TO 6508. 6-23-06: TAG WHIPSTOCK @ 6498. MILL OVER TO 6502. PULL UP TO ABOVE OLD SQZ PERF. 6-26-06: TIH W/OVERSHOT & LATCH ONTO WHIPSTOCK. 6-27-06: TIH & TAG WHIPSTOCK. TRY TO LATCH ONTO WHIPSTOCK. TOH W/TBG & BHA. GOT OUT OF HOLE W/WHIPSTOCK. 6-28-06: MIRU SAND LINE BAILER. C/O TOP OF CIBP & BEAT CIBP TO 6598'.PUSH CIBP TO 6614'. C/O TO 6675'. TIH W/BIT & TBG. 6-29-06: TAG @ 6663. ESTAB CIRC W/AIR @ 5200'. TIH & RU AIR UNIT. TRY TO CIRC W/AIR. COULD NOT CIRC. 6-30-06: TIH W/BPMJ, PERF SUB, SN, 2 7/8" TBG, TAC. TIH W/PUMP & RODS. RIG DOWN. FINAL REPORT. 							
I hereby certify that the information above SIGNATURE	use I'm	best of my knowledge and belijer. TITLE se Pinkerton	Regu	latory Specialist	·		2 <u>2006</u> 432-687-7375
(This space for State Use)					rQ.		

CONDITIONS OF APPROVAL, IF ANY:

PETROLEUM ENGINEER

DATE

DeSall 1, 17, 2006