
Office	State of New Mexic	co	Form C-103
District I	Energy, Minerals and Natural	Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		į.	WELL API NO. 30-025-06550
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE X
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 8750)5 6	o. State Oil & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		BACK TO A DESCRIPTION OF THE SUCH	'. Lease Name or Unit Agreement Name East Blinebry Drinkard Unit
1. Type of Well: Oil Well	Gas Well Other	8	3. Well Number 48
2. Name of Operator	.•	9	OGRID Number 00873
Apache Corporation 3. Address of Operator 6120 South Yale, Suite 1500		1	0. Pool name or Wildcat
5. Address of Operator 6120 South Yale, Suite 1500 Tulsa, OK 74136-4224		1	
4. Well Location			Blinebry Oil & Gas (06660)
	feet from the South	line and _660	feet from the West line
Section 12	Township 21S Range	e 37E N	NMPM CountyLea
	11. Elevation (Show whether DR, Ri	KB, RT, GR, etc.)	
Pit or Below-grade Tank Application _ o	3442'		
Pit type Depth to Groundw	···	r well Distanc	ce from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume		ruction Material
12 Check /	Appropriate Box to Indicate Natu		
			•
NOTICE OF IN			EQUENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON		REMEDIAL WORK COMMENCE DRILL	☐ ALTERING CASING ☐ ING OPNS.☐ P AND A ☐
PULL OR ALTER CASING		ASING/CEMENT J	
	1		
OTHER:		THER:Convert to I	
13. Describe proposed or comp	leted operations. (Clearly state all pert	tinent details, and g	ive pertinent dates, including estimated date
13. Describe proposed or comp	leted operations. (Clearly state all pert	tinent details, and g	
13. Describe proposed or comp of starting any proposed we or recompletion.	leted operations. (Clearly state all pert rk). SEE RULE 1103. For Multiple (tinent details, and g	ive pertinent dates, including estimated date
13. Describe proposed or comp of starting any proposed wo	leted operations. (Clearly state all pert rk). SEE RULE 1103. For Multiple (tinent details, and g	ive pertinent dates, including estimated date
13. Describe proposed or comp of starting any proposed we or recompletion.Persuant to NMOCD Case No. 1356/1/2006 MIRU. Tag cement @ 50	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project (S53). Tested casing to 250 psi, held oka	tinent details, and g Completions: Attac	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
 13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56/2/2006 Drill out cement to 5677 	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project (S53'. Tested casing to 250 psi, held okay. Drill out CIBP and clean out to PBT)	tinent details, and g Completions: Attac ay. D @ 5919'. Circ ho	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 40	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project 553'. Tested casing to 250 psi, held okay. Drill out CIBP and clean out to PBT idize. Load casing and test to 250 psi, 1000 gals 15% NEFE DxBx.	tinent details, and g Completions: Attac ay. D @ 5919'. Circ ho	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46 6/7/2006 RIH with injection packet	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project 553'. Tested casing to 250 psi, held okay. Drill out CIBP and clean out to PBT idize. Load casing and test to 250 psi, 1000 gals 15% NEFE DxBx. For and tubing. Set packer @ 5653'.	tinent details, and g Completions: Attac ay. D @ 5919'. Circ ho	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 40	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project 553'. Tested casing to 250 psi, held okay. Drill out CIBP and clean out to PBT idize. Load casing and test to 250 psi, 1000 gals 15% NEFE DxBx. For and tubing. Set packer @ 5653'.	tinent details, and g Completions: Attac ay. D @ 5919'. Circ ho	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46 6/7/2006 RIH with injection packet	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project 553'. Tested casing to 250 psi, held okay. Drill out CIBP and clean out to PBT idize. Load casing and test to 250 psi, 1000 gals 15% NEFE DxBx. For and tubing. Set packer @ 5653'.	tinent details, and g Completions: Attac ay. D @ 5919'. Circ ho	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46 6/7/2006 RIH with injection packet	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project 553'. Tested casing to 250 psi, held okay. Drill out CIBP and clean out to PBT idize. Load casing and test to 250 psi, 1000 gals 15% NEFE DxBx. For and tubing. Set packer @ 5653'.	tinent details, and g Completions: Attac ay. D @ 5919'. Circ ho	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46 6/7/2006 RIH with injection packet	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project 553'. Tested casing to 250 psi, held okay. Drill out CIBP and clean out to PBT idize. Load casing and test to 250 psi, 1000 gals 15% NEFE DxBx. For and tubing. Set packer @ 5653'.	tinent details, and g Completions: Attac ay. D @ 5919'. Circ ho	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46 6/7/2006 RIH with injection packet	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project 553'. Tested casing to 250 psi, held okay. Drill out CIBP and clean out to PBT idize. Load casing and test to 250 psi, 1000 gals 15% NEFE DxBx. For and tubing. Set packer @ 5653'.	tinent details, and g Completions: Attac ay. D @ 5919'. Circ ho	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46 6/7/2006 RIH with injection packe 6/15/2006 Lobo Trucking performe	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (0.03) Waterflood Project (0.053). Tested casing to 250 psi, held okard in the control out CIBP and clean out to PBT (1.00) gals 15% NEFE DxBx. (1.00) gals 15% NE	tinent details, and g Completions: Attac ay. D @ 5919'. Circ ho	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46 6/7/2006 RIH with injection packer 6/15/2006 Lobo Trucking performe	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project 553'. Tested casing to 250 psi, held okard in the control of the control	tinent details, and g Completions: Attac ay. D @ 5919'. Circ ho held ok.	ive pertinent dates, including estimated date h wellbore diagram of proposed completion le clean.
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46 6/7/2006 RIH with injection packer 6/15/2006 Lobo Trucking performe	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project 553'. Tested casing to 250 psi, held okard in the control of the control	completions: Attack ay. D @ 5919'. Circ howheld ok.	ive pertinent dates, including estimated date h wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46 6/7/2006 RIH with injection packer 6/15/2006 Lobo Trucking performe	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (O) Waterflood Project 553'. Tested casing to 250 psi, held okard in the control of the control	completions: Attack ay. D @ 5919'. Circ howheld ok.	ive pertinent dates, including estimated date h wellbore diagram of proposed completion le clean.
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46/7/2006 RIH with injection packe 6/15/2006 Lobo Trucking performed. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (Cork). Tested casing to 250 psi, held okard in the cork of the	inent details, and g Completions: Attac ay. D @ 5919'. Circ ho held ok.	ive pertinent dates, including estimated date h wellbore diagram of proposed completion le clean. le clean. Ind belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56 6/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 40 6/7/2006 RIH with injection packs 6/15/2006 Lobo Trucking performe I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Elaine Linton For State Use Only	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (Cork). Tested casing to 250 psi, held okard in the cork of the	inent details, and g Completions: Attac ay. D @ 5919'. Circ ho held ok.	ive pertinent dates, including estimated date h wellbore diagram of proposed completion le clean. le clean. le clean. le clean. DATE 07/14/2006 Dachecorp.comTelephone No. (918)491-5362
13. Describe proposed or comp of starting any proposed we or recompletion. Persuant to NMOCD Case No. 135 6/1/2006 MIRU. Tag cement @ 56/2/2006 Drill out cement to 5677 6/5/2006 Clean out and prep to ac 6/6/2006 Acidize Blinebry with 46/7/2006 RIH with injection packe 6/15/2006 Lobo Trucking performed. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	leted operations. (Clearly state all pertork). SEE RULE 1103. For Multiple (Cork). Tested casing to 250 psi, held okard in the cork of the	inent details, and g Completions: Attac ay. D @ 5919'. Circ ho held ok.	ive pertinent dates, including estimated date h wellbore diagram of proposed completion le clean. le clean. Ind belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan DATE 07/14/2006



Lobo Trucking, LTD

20. 15-06

त्री वर्षे केला विदेशीयोग्याच्या स्टब्स्ट्रास्ट्रा