State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-05467	
DISTRICT II	- · · · · · · · · · · · · · · · · · · ·		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
<u>DISTRICT III</u>			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreeme	int Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			North Hobbs (G/SA) Unit	
1. Type of Well:			Section 23 8. Well No. 431	
Oil Well Gas Well Other Temporarily Abandoned			451	
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.				
3. Address of Operator HCR 1 Boy 90 Denver City TX	7 70323		10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323 4. Well Location				
Unit Letter I : 2310	Feet From The South	Feet	From The East	Line
Section 23	Township 18-S	Range 37-E	NMPM	Lea County
	11. Elevation (Show whether DF, R. 3681' DF	KB, RT GR, etc.)		
Pit or Below-grade Tank Application	or Closure		VIIIIIIIII	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
	k Appropriate Box to Indicate Na			
NOTICE OF INT	ENTION TO.	2082	SEQUENT REPORT OF	:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPN	IS. PLUG & AE	BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	Т ЈОВ	
OTHER: Return well to active inje	ection	OTHER:		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any				
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
				21314152
 Drill out CIBP and cement at ±3875'. Deepen well from 4135' to 4365'. Circ clean. Run CNL/HNGS/CCL log from new TD to 3350'. 				
3. Run CNL/HNGS/CCL log from new TD to 3350'.				
4. Set treating packer and acid treat w			A.T.	
5. Run injection equipment.				58 N
Injection to commence under permit F	MX-89			设置 松
injection to commence under permit I	14174-05.		•	THE REPORT OF THE PERSON OF TH
				100
				387:73636
I hereby certify that the information above is constructed or	true and complete to the best of my know	ledge and belief. I further certify the	hat any pit or below-grade tank has	s been/will be
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	OCD-approved	
		plan	GCD-approved	
SIGNATURE MUNCLE	Minhall I)	TITLE Administrative A	Associate DATE	07/19/2006
TYPE OR PRINT NAME Mendy A. J	ohnson E-mail address:	mendy johnson@oxy.com		
For State Use Only	Definati address:	menuy johnson@oxy.com	TELEPHONE NO.	806-592-6280
CONDITIONS OF APPROVAL IT				
CONDITIONS OF APPROVAL IF ANY:			uu	2 1 2006
			JOL	M T