State of New Mexico

Form C-103

Revised 1-1-89 to Appropriate Energy, Minerals and Natural Resources Department District Office OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 WELL API NO. 2040 Pacheco St. 30-025-07689 Santa Fe, NM 87505 DISTRICT II sIndicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE X STATE DISTRICT III 6State Oil & Gas Lease No 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" South Hobbs (G/SA) Unit (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: GAS OTHER TA'D WELL WELL ₅Well No. 2Name of Operator Occidental Permian LTD 102 Pool name or Wildcat 3Address of Operator 1017 W. Stanolind Rd. Hobbs, New Mexico Hobbs (G/SA) ₄Well Location 330 North 2310 East Feet From The Unit Letter Line and Feet From The 15 19 S 38 E **NMPM** Lea Township Range County 10Elevation (Show whether DF, RKB, RT, GR, etc.) 11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON COMMENCE DRILLING OPNS CHANGE PLANS PLUG AND ANBANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 5-15-03 Tag existing CIBP @ 4036' Circ. well w/ M.L.F. Spot 35 sks of cement @ 4036'-3712' Perf @ 3257' 5-16-03 Pressured up on perfs to 1000 psi Spot 35 sks of cement @ 3310 Tag @ 3110' Perf @ 2680' 5-19-03 Pressured up on perfs to 1000 psi. Spot 35 sks of cement 2730' Tag @ 2505' 5-20-03 Perf @ 1600' Pressured up on perfs no injection rate Spot 35 sks of cement @ 1655' Tag @ 1435' Perf @ 214' Establish injection rate but no circulation to surface. Squeezed 50 sks of cement Tag @ 65' Approved as to plugging of the Well Bore. 5-21-03 Spot 15 surface plug 65'-surface Liability under bond is retained until Cut off wellhead and anchors 3'BGL. Cap well. Install dry hole marker surface restoration is completed. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Enge Tech SIGNATURE

(This space for State Use)

TYPE OR PRINT NAME

TELEPHONE NO. 397-8206

CONDITIONS OF APPROVAL IF AN

OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE