

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

May 27, 2004

WELL API NO.

30-025-05567

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
NM CE State

8. Well Number

2

9. OGRID Number

227001

10. Pool name or Wildcat

Eumont; Yates-Seven Rivers Queen

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Latigo Petroleum, Inc.

3. Address of Operator 550 W. Texas, Suite 700
Midland, TX 79701

4. Well Location

Unit Letter F : 1685 feet from the North line and 1652 feet from the West line
Section 6 Township 19S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3730'

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐


OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) RIH w/ CIBP, set @ 3600'. Cap w/ 35' cement.
- 2) Circulate hole w/ 10# mud
- 3) RIH w/ CIBP, set @ 2740'. Cap w/ 35' cement
- 4) Cut and pull 4-1/2" pipe @ 2200'. Spot 30 sx plug 2150-2250'.
- 5) Spot 40 sx cement plug, 1420-1620'
- 6) Spot 30 sx cement plug @ 450'
- 7) Spot 10 sx surface plug
- 8) Cut off wellhead, install DH marker, clean and level location

SEND SCHEMATIC NEXT TIME

**THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.**



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

Lisa Hunt

TITLE Regulatory Analyst

DATE 07/20/2006

Type or print name Lisa Hunt

For State Use Only

E-mail address: lhunt@latigopetro.com

Telephone No: (432) 684-4293

APPROVED BY:

Larry W. Wink

TITLE

DATE

Conditions of Approval (if any):