Form 3160-5 (April 2004)	DEPARTMI BUREAU OF	NITED STATES ENT OF THE INTERI F LAND MANAGEMH	ENT	BBS	ON	ORM APPROVED 1B NO. 1004-0137 ires March 31, 2007
SUNDRY NOTICES AND REPORTS ON WELLS						
	Do not use this form fo	r proposals to drill	or to re-enter an	i	NM 033312 6. If Indian, A	llottee or Tribe Name
2	abandoned well. Use Fo	orm 3160-3 (APD) fo	r such proposals.			
	SUBMIT IN TRIPLICATE	- Other instructions	s on reverse side		7. If Unit or C	A/Agreement, Name and/
. Type of Well						
Oil Well	X Gas Well Other				8. Well Name and No.	
E Name of Operat					Government A No. 1	
a. Address			3b. Phone No. (include a		9. API Well No).
P.O. BOX 2	267 Midland, Texas 7970	2	432 686 3689		30-025-21719	
. Location of We	ll (Footage, Sec., T., R., M., or Survey	v Description)			10. Field and Pool, or Exploratory Area Gramma Ridge; Morrow (Gas)	
1650 FNL &						ge, horrow (Gas)
Sec 10, T2	2S, R34E			ĺ	11. County or	Parish, State
					Lea	NM
12.		E BOX(ES) TO IND	ICATE NATURE OF	NOTICE, REPC	RT, OR OTH	HER DATA
	PE OF SUBMISSION		TY	PE OF ACTION		
	Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
. []		Alter Casing	Fracture Treat	Reclamation		
X	Subsequent Report	Casing Repair	New Construction			Well Integrity
	Final Abandonment Notice	Change Plans	Plug and Abandon	Recomplete		Other
	and Administratic Nonce	Convert to Injectio	_	Water Dispo		· · · · · · · · · · · · · · · · · · ·
Describe Pro If the propos Attach the B following cou	posed or Completed Operation (clear) sal is to deepen directionally or recom- ond under which the work will be pe- muletion of the involved operations	ly state all pertinent detail plete horizontally, give su rformed or provide the B	s, including estimated starting bsurface locations and meas ond No. on file with BLM/	ng date of any prop sured and true vertic /BIA. Required sub	osed work and a cal depths of all osequent reports	approximate duration the pertinent markers and zo shall be filed within 30
following con testing has be determined th 7/02/06	Minimum Service the work will be per mpletion of the involved operations. een completed. Final Abandonment I hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H pluce	rformed or provide the B If the operation results in Notices shall be filed only in P&A operation 7.	ond No. on file with BLM, a multiple completion or re y after all requirements, inc s. RTH w/ coil to	BIA. Required sub- completion in a net cluding reclamation,	w interval, a Fo have been con	shall be filed within 30 rm 3160-4 shall be filed o ppleted, and the operator
following con testing has be determined th 7/02/06	MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'.	rformed or provide the B If the operation results in Notices shall be filed only in P&A operation 7.	ond No. on file with BLM, a multiple completion or re y after all requirements, inc s. RTH w/ coil to	BIA. Required sub- completion in a net cluding reclamation,	w interval, a Fo have been con	shall be filed within 30 d rm 3160-4 shall be filed c ppleted, and the operator
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06	MIRU BJ services to beg MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday.	rformed or provide the B If the operation results in Notices shall be filed only ction.) Jin P&A operation J. 396'. POCH w/ coi	ond No. on file with BLM, a multiple completion or re y after all requirements, inc s. RIH w/ coil tu l tubing. RIH w/	BIA. Required sub- completion in a net cluding reclamation,	w interval, a Fo have been con	shall be filed within 30 rm 3160-4 shall be filed o ppleted, and the operator
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06	ond under which the work will be per mpletion of the involved operations. een completed. Final Abandonment 1 hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POOH laying down 357 jt	rformed or provide the B If the operation results in Notices shall be filed only ction.) Jin P&A operation J. 296'. POCH w/ coi as old 2 3/8" tub	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil tu l tubing. RIH w/	BIA. Required sub- completion in a ne- cluding reclamation,	w interval, a Fo have been con	shall be filed within 30 rm 3160-4 shall be filed o ppleted, and the operator
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06	ond under which the work will be per mpletion of the involved operations. I een completed. Final Abandonment I hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. FOOH laying down 357 jt Set 50 sx Neat cement p	rformed or provide the B If the operation results in Notices shall be filed only ction.) Jin P&A operation J. 296'. POCH w/ coi as old 2 3/8" tub olucy from 12020'	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil tu l tubing. RIH w/ ing.	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter a	sequent reports winterval, a Fo have been con 0'. nd cut exci	shall be filed within 30 d rm 3160-4 shall be filed c ppleted, and the operator
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06	ond under which the work will be per mpletion of the involved operations. Here completed. Final Abandonment 1 hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A operation g. 996'. POOH w/ coi cs old 2 3/8" tube olug from 12020' 172'. Spot 50 sx	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil to l tubing. RIH w/ ing. to 11820'. Neat cement plug	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter a	sequent reports winterval, a Fo have been con 0'. nd cut exci	shall be filed within 30 d shall be filed within 30 d rm 3160-4 shall be filed d upleted, and the operator sting 2 3/8"
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/10/06 7/11/06	ond under which the work will be permission of the involved operations. Impletion of the involved operations. In the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement ; Spot 50 sx Neat cement ;	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A operation g. 996'. POCH w/ coi cs old 2 3/8" tub plug from 12020' plug from 10064' plug from 8400'	ond No. on file with BLM, a multiple completion or re y after all requirements, inc s. RIH w/ coil tu l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. to 8200'.	BIA. Required sub- completion in a new luding reclamation, abing to 1275 jet cutter at from 11650'	A cut excit sequent reports winterval, a Fo have been con 0'. nd cut excit A P [to 1f450'.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8"
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/10/06 7/11/06	ond under which the work will be permipletion of the involved operations. magnetion of the involved operations. Here completed. Final Abandonment is hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement ; Spot 50 sx Neat cement ; Parforate squeeze holes	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A operation g. 996'. POCH w/ coi cs old 2 3/8" tub olug from 12020' (72'. Spot 50 sx plug from 10064' plug from 8400' to 55	ond No. on file with BLM, a multiple completion or re y after all requirements, inc s. RIH w/ coil tu l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. to 8200'.	BIA. Required sub- completion in a new luding reclamation, abing to 1275 jet cutter at from 11650'	A cut excit sequent reports winterval, a Fo have been con 0'. nd cut excit A P [to 1f450'.	shall be filed within 30 d shall be filed within 30 d rm 3160-4 shall be filed d upleted, and the operator sting 2 3/8"
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06 7/11/06 7/12/06	ond under which the work will be permipletion of the involved operations. mpletion of the involved operations. Here completed. Final Abandonment of that the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement ; Spot 50 sx Neat cement ; Perforate squeeze holes Set 7 5/8" cement retain	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A cperation g. 996'. POCH w/ coi as old 2 3/8" tub olug from 12020' 72'. Spot 50 sx plug from 10064' plug from 8400' (from 5900' to 59 mer at 5850'.	ond No. on file with BLM, a multiple completion or re y after all requirements, inc s. RIH w/ coil tu l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. to 8200'. 902'. 8 holes tota	BIA. Required sub- completion in a new luding reclamation, abing to 1275 jet cutter at from 11650'	A cut excit sequent reports winterval, a Fo have been con 0'. nd cut excit A P [to 1f450'.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8"
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06 7/11/06 7/12/06	ond under which the work will be per mpletion of the involved operations. I een completed. Final Abandonment I hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement j Spot 50 sx Neat cement j Perforate squeeze holes Set 7 5/8" cement retain Pumped 900 sx 50/50 POZ	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A cperation g. 996'. POOH w/ coi as old 2 3/8" tube olug from 12020' 72'. Spot 50 sax plug from 10064' plug from 8400' fo from 5900' to 59 ner at 5850'. Cement through a	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil to l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. co 8200'. 302'. 8 holes tota	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter at from 11650. [1.	to 1f450.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8" PROVED L 2 8 2006 ES BABYAK
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06 7/11/06 7/12/06	ond under which the work will be permipletion of the involved operations. Impletion of the involved operations. Hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement ; Spot 50 sx Neat cement ; Perforate squeeze holes Set 7 5/8" cement retain Pumped 900 sx 50/50 POZ Sting cut of retainer an	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A operation g. 996'. POOH w/ coi cs cld 2 3/8" tub blug from 12020' 72'. Spot 50 sx plug from 10064' plug from 8400' for if from 5900' to 59 mer at 5850'. cement through p nd spot 50 sx New	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil to l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. co 8200'. 202'. 8 holes tota retainer.	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter at from 11650. [1.	to 1f450.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8" PROVED L 2 & 2006
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06 7/11/06 7/12/06	ond under which the work will be per mpletion of the involved operations. I een completed. Final Abandonment I hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement j Spot 50 sx Neat cement j Perforate squeeze holes Set 7 5/8" cement retain Pumped 900 sx 50/50 POZ	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A operation g. 996'. POOH w/ coi as old 2 3/8" tub plug from 12020' 72'. Spot 50 sx plug from 10064' plug from 10064' plug from 8400' to 59 mer at 5850'. cement through p nd spot 50 sx Ness plug from 3700' to	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil to l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. co 8200'. 202'. 8 holes tota retainer.	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter at from 11650. [1.	to 1f450.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8" PROVED L 2 8 2006 ES BABYAK
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/05/06 7/10/06 7/11/06 7/11/06 7/12/06 7/13/06	ond under which the work will be permipletion of the involved operations. een completed. Final Abandonment 1 hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement ; Spot 50 sx Neat cement ; Spot 50 sx Neat cement ; Perforate squeeze holes Set 7 5/8" cement retain Pumped 900 sx 50/50 POZ Sting cut of retainer an Spot 25 sx Neat cement ; Perforate from 450' to 4	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A operation g. 996'. POOH w/ coi as old 2 3/8" tub plug from 12020' 72'. Spot 50 sx plug from 10064' plug from 10064' plug from 8400' to 59 mer at 5850'. cement through p nd spot 50 sx Ness plug from 3700' to	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil to l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. co 8200'. 202'. 8 holes tota retainer.	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter at from 11650. [1.	to 1f450.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8" PROVED L 2 8 2006 ES BABYAK
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06 7/11/06 7/12/06 7/13/06	ond under which the work will be permipletion of the involved operations. een completed. Final Abandonment 1 hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POCH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement j Perforate squeeze holes Set 7 5/8" cement retain Pumped 900 sx 50/50 POZ Sting cut of retainer an Spot 25 sx Neat cement j Perforate from 450' to 4 that the foregoing is true and correct Spod)	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A operation g. 996'. POOH w/ coi as old 2 3/8" tub plug from 12020' 72'. Spot 50 sx plug from 10064' plug from 10064' plug from 8400' to 59 mer at 5850'. cement through p nd spot 50 sx Ness plug from 3700' to	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil to l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. to 8200'. 202'. 8 holes tota retainer. at cement plug from to 3600'. Title	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter ar from 11650' t 1. n 5850' to 58	to 1f450.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8" PROVED L 2 8 2006 ES BABYAK
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06 7/11/06 7/11/06 7/12/06 7/12/06 7/13/06	ond under which the work will be permipletion of the involved operations. een completed. Final Abandonment 1 hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. POOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement ; Spot 50 sx Neat cement ; Perforate squeeze holes Set 7 5/8" cement retain Pumped 900 sx 50/50 POZ Sting cut of retainer an Spot 25 sx Neat cement ; Perforate from 450' to 4 that the foregoing is true and correct Sped)	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A operation g. 996'. POOH w/ coi as old 2 3/8" tub plug from 12020' 72'. Spot 50 sx plug from 10064' plug from 10064' plug from 8400' to 59 mer at 5850'. cement through p nd spot 50 sx Ness plug from 3700' to	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil tu l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. to 8200'. 202'. 8 holes tota retainer. th cement plug from to 3600'. Title Regulat	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter at from 11650. [1.	to 1f450.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8" PROVED L 2 8 2006 ES BABYAK
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06 7/11/06 7/11/06 7/12/06 7/12/06 7/13/06	ond under which the work will be permipletion of the involved operations. een completed. Final Abandonment 1 hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. FOOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement j Perforate squeeze holes Set 7 5/8" cement retain Pumped 900 sx 50/50 POZ Sting cut of retainer an Spot 25 sx Neat cement j Perforate from 450' to 4 that the foregoing is true and correct yped) Mumped	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A cperation g. 996'. POOH w/ coi as old 2 3/8" tub plug from 12020' 72'. Spot 50 sx plug from 10064' plug from 10064' plug from 8400' to 59 mer at 5850'. cement through p nd spot 50 sx New plug from 3700' to 452'.	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil to l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. to 8200'. 202'. 8 holes tota retainer. at cement plug from to 3600'. Title Regulate Date 07/25/06	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter at from 11650' to 1. n 5850' to 58 ory Analyst	to 1f450.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8" PROVED L 2 8 2006 ES BABYAK
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06 7/11/06 7/11/06 7/12/06 7/12/06 7/13/06	ond under which the work will be permipletion of the involved operations. een completed. Final Abandonment 1 hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. FOOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement j Perforate squeeze holes Set 7 5/8" cement retain Pumped 900 sx 50/50 POZ Sting cut of retainer an Spot 25 sx Neat cement j Perforate from 450' to 4 that the foregoing is true and correct yped) Mumped	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A cperation g. 996'. POOH w/ coi as old 2 3/8" tub plug from 12020' 72'. Spot 50 sx plug from 10064' plug from 10064' plug from 8400' to 59 mer at 5850'. cement through p nd spot 50 sx New plug from 3700' to 452'.	ond No. on file with BLM a multiple completion or re y after all requirements, inc s. RIH w/ coil tu l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. to 8200'. 202'. 8 holes tota retainer. th cement plug from to 3600'. Title Regulat. Date 07/25/06 RAL OR STATE OFFI	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter at from 11650' to 1. n 5850' to 58 ory Analyst	to 1f450.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8" PROVED L 2 8 2006 ES BABYAK
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/05/06 7/10/06 7/10/06 7/11/06 7/12/06 7/12/06 7/13/06	ond under which the work will be permipletion of the involved operations. een completed. Final Abandonment 1 hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. FOOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement j Perforate squeeze holes Set 7 5/8" cement retain Pumped 900 sx 50/50 POZ Sting cut of retainer an Spot 25 sx Neat cement j Perforate from 450' to 4 that the foregoing is true and correct yped) Magner Magner THIS	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A cperation g. 996'. POOH w/ coi as old 2 3/8" tub plug from 12020' 72'. Spot 50 sx plug from 10064' plug from 8400' to from 5900' to 59 mer at 5850'. cement through p nd spot 50 sx New plug from 3700' to 452'.	ond No. on file with BLM a multiple completion or re- y after all requirements, inc s. RIH w/ coil to l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. to 8200'. 202'. 8 holes tota retainer. at cement plug from to 3600'. Title Regulate Date 07/25/06 RAL OR STATE OFFI	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter at from 11650' to 1. n 5850' to 58 ory Analyst	to 1f450.	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8" PROVED L 2 8 2006 ES BABYAK
Attach the B following con testing has b determined th 7/02/06 7/03/06 7/04/06 7/05/06 7/10/06 7/11/06 7/11/06 7/12/06 7/12/06 7/13/06	ond under which the work will be permipletion of the involved operations. een completed. Final Abandonment 1 hat the final site is ready for final inspe- MIRU BJ services to beg Pump 50 sx Class H plug RIH & tag cement at 119 tubing at 12000'. Shut down for holiday. FOOH laying down 357 jt Set 50 sx Neat cement p RIH & tag cement at 117 Spot 50 sx Neat cement j Perforate squeeze holes Set 7 5/8" cement retain Pumped 900 sx 50/50 POZ Sting cut of retainer an Spot 25 sx Neat cement j Perforate from 450' to 4 that the foregoing is true and correct yped) Mumped	rformed or provide the B If the operation results in Notices shall be filed only ction.) gin P&A cperation g. 996'. POOH w/ coi as old 2 3/8" tub olug from 12020' (72'. Spot 50 sx plug from 10064' plug from 8400' to 59 ner at 5850'. cement through p nd spot 50 sx New plug from 3700' to 452'. SPACE FOR FEDEN	ond No. on file with BLM, a multiple completion or re- y after all requirements, inc s. RIH w/ coil tu- l tubing. RIH w/ ing. to 11820'. Neat cement plug to 9864'. to 8200'. 202'. 8 holes tota retainer. th cement plug from to 3600'. Title Date 07/25/06 RAL OR STATE OFFI	BIA. Required sub ecompletion in a ner- luding reclamation, abing to 1275 jet cutter at from 11650' to 1. n 5850' to 58 ory Analyst	a dephis of an sequent reports winterval, a Fo have been con 0'. nd cut excl to 1f450'. JU 550'.PETRO	shall be filed within 30 of shall be filed within 30 of m3160-4 shall be filed of pleted, and the operator sting 2 3/8" PROVED L 2 8 2006 ES BABYAK

GWW

Form 3160-5 (April 2004)	DEPARTME	ITED STATES ENT OF THE INTERIOR LAND MANAGEMENT			OMB	M APPROVED NO. 1004-0137 is March 31, 2007	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.						NM 033312 6. If Indian, Allottee or Tribe Name	
1 There - 6 W/ 11	SUBMIT IN TRIPLICATE -	Other instruction	s on reverse side		7. If Unit or CA	Agreement, Name and/or No	
					8. Well Name and No. Government A No. 1		
EOG Resources Inc. 3a. Address P.O. Box 2267 Midland, Texas 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1650 FNL & 1650 FWL Sec 10, T22S, R34E			3b. Phone No. (<i>include ar</i> 432 686 3689	rea code)	 9. API Well No. 30-025-21719 10. Field and Pool, or Exploratory Area Gramma Ridge; Morrow (Gas) 		
					11. County or Parish, State		
12.	CHECK APPROPRIATE	BOX(ES) TO INE	DICATE NATURE OF I	NOTICE, REP		NM	
ТҮРЕ	OF SUBMISSION	TYPE OF ACTION					
x su	otice of Intent ubsequent Report nal Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction New Abandon Plug Back	Reclamation	plete Other		

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

7/13/06 Spot 250 sx Neat cement plug. Circulated cement from perforations at 450' to surface.

7/14/06 Dig out cellar. Out casing off and weld on dry hole marker. P&A 7/13/06.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) 7	Title						
Stap/Wagner	Regulatory Analyst						
Marlagn	Date 07/25/06						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by	Title	Date					
Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject le which would entitle the applicant to conduct operations thereon.	t or Office ase						
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for a States any false, fictitious or fraudulent statements or representations as to any matter y	any person knowingly and willfully to make to any deputition	partment or agency of the United					