

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-10080
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-9089
7. Lease Name or Unit Agreement Name Penrock New Mexico BW State
8. Well Number 1
9. OGRID Number 175260
10. Pool name or Wildcat Tobac Pennsylvanian

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Judah Oil	
3. Address of Operator P.O. Box 568 Artesia, NM 88211-0568	
4. Well Location K <u>1810</u> feet from the <u>N</u> line and <u>500</u> feet from the <u>W</u> line Unit Letter <u>1874</u> Section 20 Township 8S Range 33E NMPM County Chaves	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>	
Pit type	Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water
Pit Liner Thickness:	mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Propose to put well back on production

1. Move in pulling unit and rig up
2. Run in hole with 2 3/8 tubing and AD-1 packer
3. Tag bottom
4. Set packer @ 8975
5. Pump 1000 gal Xylene, 50 bbls hot oil, 30 bbls hot wtr, 165 gal SU-325 acid-surf
6. Pull tbq and packer
7. RIH with SN 2 3/8 tubing, pump and rods.
8. Put well on production

Work will began July-11-2006

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.
Owner
07-02-2006

SIGNATURE _____ TITLE _____ DATE _____

Type or print name James B Campanella E-mail address: wwwjudahoil@yahoo.com Telephone No (505)746-1280
For State Use Only

APPROVED BY: Harry W. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER
Conditions of Approval (if any):

DATE
AUG 04 2006