Submit 3 Copies To Appropriate District Office	State of New						Form C-103
District I	Energy, Minerals and	Inatural Res	Juices	WELL AP	I NO	Revised	March 25, 1999
1625 N. French Dr., Hobbs, NM 87240 District II	OIL CONSERVA		SION	30-025-33333			
811 South First, Artesia, NM 87210 District III 2040 South Pacheco				5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505				STA	TE I	FEE	
District IV 2040 South Pacheco, Santa Fe, NM 87505				6. State Oil & Gas Lease No. B-155-1			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					lame or Un	it Agreen	nent Name:
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other				Central Vacuum Unit			
2. Name of Operator	Other	·····		8. Well N	0.		
Chevron U.S.A. Inc.				179			
3. Address of Operator					me or Wild	lcat	
15 Smith Road - Midland, Texas	79705			Vacum G	cayburg Sa	an Andre	8
4. Well Location							
Unit Letter <u>L</u> : 19	97 feet from the	South	line and	1263	feet from t	heWe	estline
Section 36	Township 17-	U	34-E	NMPM		County	lea
	0. Elevation (Show whe	ether DR, RK. 3999' GL	B, RT, GR, ei	tc.)	n Berner		
11 Charles Ann	propriate Box to Ind		ofNation	Donort o	r Othor D	oto	
**	-			1 ,			
NOTICE OF INTEN PERFORM REMEDIAL WORK	LUG AND ABANDON		SUE DIAL WORK	SEQUEN			: G CASING
	HANGE PLANS	С сомм	ENCE DRILL	ING OPNS.		PLUG AN ABANDO	
	NULTIPLE COMPLETION		G TEST AND NT JOB				
e e e e e e e e e e e e e e e e e e e		1					
DTHER:			R: Convert	to Sub Pur	P		
	perations (Clearly state	OTHER all pertinent	R: Convert details, and g	ive pertinen	t dates, incl	-	mated date
DTHER: 12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation. 06-06-03 MIRU. 06-09-03 Rig pump up on the	perations (Clearly state ERULE 1103. For Mu g & pumped 80 bbls	OTHER all pertinent litiple Comple brine water	Convert details, and g tions: Attack	ive pertinen 1 wellbore di 211; put w	t dates, incl agram of pr	roposed co	mated date ompletion
DTHER: 12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation. 06-06-03 MIRU. 06-09-03 Rig pump up on the packer @ 4271' & 1 06-10-03 TCH w/80 jts thg,	perations (Clearly state E RULE 1103. For Mu	OTHER all pertinent ltiple Comple brine water	Convert details, and g tions: Attack to kill w i loc set p	ive pertinen a wellbore di ell; put w acker. TI	t dates, incl agram of pr ell on va H w/80-jt	cum. R stbg to t unit u	mated date completion el 2515'. p for
DTHER: 12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation. 06-06-03 MIRU. 06-09-03 Rig pump up on the packer @ 4271' &	perations (Clearly state E RULE 1103. For Mu g & pumped 80 bbls TOH w/168 jts 2-7/8 kill string. TIH	OTHER all pertinent ltiple Comple brine water	Convert details, and g tions: Attack to kill w i loc set p	ell; put w acker. TI otor @ 431	t dates, incl agram of pr ell on va H w/80-jt	cum. R stbg to t unit, y	mated date completion el
DTHER: 12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation. 06-06-03 MIRU. 06-09-03 Rig pump up on the packer @ 4271' & 06-10-03 TOH w/80 jts the, test run (good).	perations (Clearly state E RULE 1103. For Mu g & pumped 80 bbls TOH w/168 jts 2-7/8 kill string. TIH	OTHER all pertinent ltiple Comple brine water	Convert details, and g tions: Attack to kill w i loc set p	ell; put w acker. TI otor @ 431	t dates, incl agram of pr ell on va H w/80 jt Star gg00 sqq00 (7.1	cum. R stbg to t unit, y	mated date completion el 2515'. p for
DTHER: 12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation. 06-06-03 MIRU. 06-09-03 Rig pump up on the packer @ 4271' & 06-10-03 TOH w/80 jts the, test run (good).	perations (Clearly state E RULE 1103. For Mu g & pumped 80 bbls TOH w/168 jts 2-7/8 kill string. TIH	OTHER all pertinent ltiple Comple brine water	Convert details, and g tions: Attack to kill w i loc set p	ive pertinen a wellbore di ell; put w acker. TI otor @ 431	t dates, incl agram of pr ell on va H w/80-jt 912 Star 000 sqq01	cum. R stbg to t unit, y	mated date ompletion
<ul> <li>DTHER:</li> <li>12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation.</li> <li>06-06-03 MIRU.</li> <li>06-09-03 Rig pump up on the packer @ 4271' &amp; '</li> <li>06-10-03 TOH w/80 jts tbg, test run (good).</li> </ul>	perations (Clearly state E RULE 1103. For Mu g & pumped 80 bbls TOH w/168 jts 2-7/8 kill string. TIH	OTHER all pertinent ltiple Comple brine water	Convert details, and g tions: Attack to kill w i loc set p	ell; put w acker. TI otor @ 431	t dates, incl agram of pr ell on va H w/80 jt Star gg00 sqq00 (7.1	cum. R stbg to t unit, y	mated date ompletion
DTHER: 12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation. 06-06-03 MIRU. 06-09-03 Rig pump up on the packer @ 4271' & 06-10-03 TOH w/80 jts the, test run (good).	perations (Clearly state E RULE 1103. For Mu g & pumped 80 bbls TOH w/168 jts 2-7/8 kill string. TIH	OTHER all pertinent ltiple Comple brine water	Convert details, and g tions: Attack to kill w i loc set p	ell; put w acker. TI otor @ 431	t dates, incl agram of pr ell on va H w/80 jt Star gg00 sqq00 (7.1	conum. R stbg to t unit y gfN	mated date ompletion
DTHER: 12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation. 06-06-03 MIRU. 06-09-03 Rig pump up on the packer @ 4271' & 06-10-03 TOH w/80 jts theg, test run (good). 06-11-03 RD. FINAL REPORT	perations (Clearly state E RULE 1103. For Mu g & pumped 80 bbls TOH w/168 jts 2-7/8 kill string. TIH	OTHER all pertinent liple Comple brine water " tbg, SN a w/sub pump.	Convert details, and g tions: Attack to kill w loc set p Bottom m	ell; put w acker. TT otor @ 431	t dates, incl agram of pr ell on va H w/80 Jt Star 030 sqq00 03 ENZ	conum. R stbg to t unit y gfN	mated date ompletion
DTHER: 12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation. 06-06-03 MIRU. 06-09-03 Rig pump up on the packer @ 4271' & 1 06-10-03 TOH w/80 jts thg, test run (good). 06-11-03 RD. FINAL REPORT hereby certify that the information above is the	perations (Clearly state E RULE 1103. For Mu g & pumped 80 bbls TOH w/168 jts 2-7/8 kill string. TIH	OTHER all pertinent liple Comple brine water " tbg, SN a w/sub pump.	R: Convert details, and g tions: Attack to kill w loc set p Bottom m	tive pertinent a wellbore di ell; put w acker. TH otor @ 431	t dates, incl agram of pr ell on va H w/80-jt Star 030 sqq00 03 <sup>1</sup> EW	cum. R stbg to t unit, y f f f N	mated date ompletion
DTHER:         12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation.         06-06-03       MIRU.         06-09-03       Rig pump up on the packer (e 4271' & 106-10-03)         06-10-03       TOH w/80 jts thg, test run (good).         06-11-03       RD.         FINAL REPORT	perations (Clearly state E RULE 1103. For Mu g & pumped 80 bbls TCH w/168 jts 2-7/8 kill string. TIH	OTHER all pertinent liple Complet brine water " tbg, SN & w/sub pump.	R: Convert details, and g tions: Attack to kill w i loc set p Bottom m	tive pertinent a wellbore di ell; put w acker. TH otor @ 431	t dates, incl agram of pr ell on va H w/80 jt Star 030 500 031 EW EW DA	TE	mated date completion
DTHER:         12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation.         06-06-03       MIRU.         06-09-03       Rig pump up on the packer @ 4271' & 10000000000000000000000000000000000	perations (Clearly state E RULE 1103. For Mu g & pumped 80 bbls TCH w/168 jts 2-7/8 kill string. TIH	OTHER all pertinent liple Complet brine water " tbg, SN & w/sub pump.	R: Convert details, and g tions: Attack to kill w i loc set p Bottom m	tive pertinent a wellbore di ell; put w acker. TH otor @ 431	t dates, incl agram of pr ell on va H w/80 jt Star 030 500 031 EW EW DA	TE	mated date completion
DTHER: 12. Describe Proposed or Completed O of starting any proposed work). SE or recompilation. 06-06-03 MIRU. 06-09-03 Rig pump up on the packer @ 4271' & 1 06-10-03 TOH w/80 jts theg, test run (good). 06-11-03 RD. FINAL REPORT hereby certify that the information above is the	perations (Clearly state E RULE 1103. For Mu g & pumped 80 bbls TCH w/168 jts 2-7/8 kill string. TIH	OTHER all pertinent liple Complet brine water " tbg, SN 4 w/sub pump.	R: Convert details, and g tions: Attack to kill w i loc set p Bottom m	tive pertinent a wellbore di ell; put w acker. TH otor @ 431	t dates, incl agram of pr ell on va H w/80 jt Star 030 500 031 EW EW DA	TTE OF	mated date completion

1