Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR

OCD-HOBBS

FORM APPROVED OM B No. 1004-0137

Expires: March 31, 2	
Lease Serial No	

BUREAU OF LAND MANAGEMENT		5. Lease Serial No. NMNM 04229C
SUNDRY NOTICES AND REPORTS O Do not use this form for proposals to drill or abandoned well. Use Form 3160-3 (APD) for s	to re-enter an	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions of	n reverse side.	7. If Unit or CA/Agreement, Name and/or No.
l. Type of Well ☐ Oil Well ☐ Gas Well ☐ Other		8. Well Name and No.
2. Name of Operator CHESAPEAKE OPERATING, INC. ATTN: I	JINDA GOOD	LITTLE EDDY UNIT 7
Ra Address 3b. Phone N P. O. BOX 18496, OKLAHOMA CITY, OK 73154-0496 405-767-	o. (include area códe) 12 73 74	9. API Well No. 30-025-32629 S No. Field and Pool, or Exploratory Area C HAT MESA; DELAWARE
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	/6° \$	6 HAT MESA; DELAWARE
12. CHECK APPROPRIATE BOX(ES) TO INDICATE TYPE OF SUBMISSION	19 Sept 20 18	1 County or Parish, State
12. CHECK APPROPRIATE BOX(ES) TO INDICATE	NATURE OF NOTICE, F	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	A. A
Acidize	reat Reclamation	Water Shut-Off Well Integrity Other Open add'l. perfs
☐ Final Abandonment Notice ☐ Change Plans ☐ Plug and A ☐ Convert to Injection ☐ Plug Back	Abandon Temporarily A	
13. Describe Proposed or Completed Operation (clearly state all pertinent details, inc. If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a roun.	ace locations and measured and tro. on file with BLM/BIA. Requi	rue vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RUE M Hobbs Wireline. Set CIBP @ 7260'. Press test Delaware I Sand from 7122' - 7136' w/2 JSPF, 28 holes. Pumped 100	ace locations and measured and tro. on file with BLM/BIA. Requitiple completion or recompletion all requirements, including reclared csg & CIBP to 3000 psi, O. 0 gal 7 1/2% HCL acid.	nue vertical depths of all pertinent markers and zones, red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RUE M Hobbs Wireline. Set CIBP @ 7260'. Press testing the properties of the proposal set of the properties o	ace locations and measured and tro. on file with BLM/BIA. Requitiple completion or recompletion all requirements, including reclared csg & CIBP to 3000 psi, O. 0 gal 7 1/2% HCL acid.	nue vertical depths of all pertinent markers and zones, red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in 3000 psi. Frac'd Delaware I Sand from
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RUEM Hobbs Wireline. Set CIBP @ 7260'. Press test Delaware I Sand from 7122' - 7136' w/2 JSPF, 28 holes. Pumped 100 7/10/2006 RUBJ Services. Tested treating lines to 5000 psi. Set ki	ace locations and measured and tro. on file with BLM/BIA. Requiliple completion or recompletion all requirements, including reclared csg & CIBP to 3000 psi, O.0 gal 7 1/2% HCL acid. Ils to 3000 psi. Set pop-off to	nue vertical depths of all pertinent markers and zones, red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in 3000 psi. Frac'd Delaware I Sand from
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RU E M Hobbs Wireline. Set CIBP @ 7260'. Press test Delaware I Sand from 7122' - 7136' w/2 JSPF, 28 holes. Pumped 100 7/10/2006 RU BJ Services. Tested treating lines to 5000 psi. Set ki 7122' - 7136' w/112,787 gal PW 10,000# 14/30 Lite Prop.	ace locations and measured and tro. on file with BLM/BIA. Requiliple completion or recompletion all requirements, including reclar ed csg & CIBP to 3000 psi, O. 0 gal 7 1/2% HCL acid. Ils to 3000 psi. Set pop-off to 7181'. Circ hole clean for 2	nue vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in 3000 psi. Frac'd Delaware I Sand from ACCEPTED FOR RECOR
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RU E M Hobbs Wireline. Set CIBP @ 7260'. Press test: Delaware I Sand from 7122' - 7136' w/2 JSPF, 28 holes. Pumped 100 7/10/2006 RU BJ Services. Tested treating lines to 5000 psi. Set ki 7122' - 7136' w/112,787 gal PW 10,000# 14/30 Lite Prop. 7/11/2006 Tagged fill @ 7261'. Cleaned out fill and tagged CIBP @ 7261'.	ace locations and measured and tro. on file with BLM/BIA. Requiliple completion or recompletion all requirements, including reclar ed csg & CIBP to 3000 psi, O. 0 gal 7 1/2% HCL acid. Ils to 3000 psi. Set pop-off to 7181'. Circ hole clean for 2	nue vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in 3000 psi. Frac'd Delaware I Sand from ACCEPTED FOR RECOR thrs w/foam unit. AUG 4 2006
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RU E M Hobbs Wireline. Set CIBP @ 7260'. Press test Delaware I Sand from 7122' - 7136' w/2 JSPF, 28 holes. Pumped 100 7/10/2006 RU BJ Services. Tested treating lines to 5000 psi. Set ki 7122' - 7136' w/112,787 gal PW 10,000# 14/30 Lite Prop. 7/11/2006 Tagged fill @ 7261'. Cleaned out fill and tagged CIBP @ 7/12/2006 RIH w/2 7/8" J-55 tubing, seating nipple @ 7171'. PU p	ace locations and measured and tro. on file with BLM/BIA. Requiliple completion or recompletion all requirements, including reclar ed csg & CIBP to 3000 psi, O. 0 gal 7 1/2% HCL acid. Ils to 3000 psi. Set pop-off to 7181'. Circ hole clean for 2	nue vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in 3000 psi. Frac'd Delaware I Sand from ACCEPTED FOR RECOR thrs w/foam unit. 11 well on production.
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RU E M Hobbs Wireline. Set CIBP @ 7260'. Press test Delaware I Sand from 7122' - 7136' w/2 JSPF, 28 holes. Pumped 100 7/10/2006 RU BJ Services. Tested treating lines to 5000 psi. Set ki 7122' - 7136' w/112,787 gal PW 10,000# 14/30 Lite Prop. 7/11/2006 Tagged fill @ 7261'. Cleaned out fill and tagged CIBP @ 7/12/2006 RIH w/2 7/8" J-55 tubing, seating nipple @ 7171'. PU public Prop. BLM NATIONWIDE BOND #NM2634.	ace locations and measured and tro. on file with BLM/BIA. Requiliple completion or recompletion all requirements, including reclar ed csg & CIBP to 3000 psi, O. 0 gal 7 1/2% HCL acid. Ils to 3000 psi. Set pop-off to 7181'. Circ hole clean for 2	nue vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in 3000 psi. Frac'd Delaware I Sand from ACCEPTED FOR RECOR thrs w/foam unit. AUG 4 2006 LES BABYAK
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RU E M Hobbs Wireline. Set CIBP @ 7260'. Press tests Delaware I Sand from 7122' - 7136' w/2 JSPF, 28 holes. Pumped 100 7/10/2006 RU BJ Services. Tested treating lines to 5000 psi. Set ki 7122' - 7136' w/112,787 gal PW 10,000# 14/30 Lite Prop. 7/11/2006 Tagged fill @ 7261'. Cleaned out fill and tagged CIBP @ 7/12/2006 RIH w/2 7/8" J-55 tubing, seating nipple @ 7171'. PU public bloom PNM2634. (CHK PN 891309)	ace locations and measured and tro. on file with BLM/BIA. Requiliple completion or recompletion all requirements, including reclar ed csg & CIBP to 3000 psi, O. 0 gal 7 1/2% HCL acid. Ils to 3000 psi. Set pop-off to 7181'. Circ hole clean for 2	nue vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in 3000 psi. Frac'd Delaware I Sand from ACCEPTED FOR RECOR thrs w/foam unit. AUG 4 2006 LES BABYAK PETROLEUM ENGINEER
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RU E M Hobbs Wireline. Set CIBP @ 7260'. Press tests Delaware I Sand from 7122' - 7136' w/2 JSPF, 28 holes. Pumped 100 7/10/2006 RU BJ Services. Tested treating lines to 5000 psi. Set ki 7122' - 7136' w/112,787 gal PW 10,000# 14/30 Lite Prop. 7/11/2006 Tagged fill @ 7261'. Cleaned out fill and tagged CIBP @ 7/12/2006 RIH w/2 7/8" J-55 tubing, seating nipple @ 7171'. PU public Properties of the properties of th	ace locations and measured and tro. on file with BLM/BIA. Requiliple completion or recompletion all requirements, including reclar ed csg & CIBP to 3000 psi, O. 10 gal 7 1/2% HCL acid. Ils to 3000 psi. Set pop-off to 7181'. Circ hole clean for 2 pump 2 1/2" x 1-3/4" x 20', pu	nue vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in 3000 psi. Frac'd Delaware I Sand from ACCEPTED FOR RECOR thrs w/foam unit. AUG 4 2006 LES BABYAK PETROLEUM ENGINEER
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RU E M Hobbs Wireline. Set CIBP @ 7260'. Press tests Delaware I Sand from 7122' - 7136' w/2 JSPF, 28 holes. Pumped 100 7/10/2006 RU BJ Services. Tested treating lines to 5000 psi. Set ki 7122' - 7136' w/112,787 gal PW 10,000# 14/30 Lite Prop. 7/11/2006 Tagged fill @ 7261'. Cleaned out fill and tagged CIBP @ 7/12/2006 RIH w/2 7/8" J-55 tubing, seating nipple @ 7171'. PU public BLM NATIONWIDE BOND #NM2634. (CHK PN 891309)	ace locations and measured and tro. on file with BLM/BIA. Requiliple completion or recompletion all requirements, including reclar and case & CIBP to 3000 psi, O 10 gal 7 1/2% HCL acid. Ils to 3000 psi. Set pop-off to 20 7181'. Circ hole clean for 2 20 ymp 2 1/2" x 1-3/4" x 20', pto Title PERMITTING AGE	nue vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in 3000 psi. Frac'd Delaware I Sand from ACCEPTED FOR RECOR thrs w/foam unit. AUG 4 2006 LES BABYAK PETROLEUM ENGINEER CNT 07/18/2006
If the proposal is to deepen directionally or recomplete horizontally, give subsurf Attach the Bond under which the work will be performed or provide the Bond N following completion of the involved operations. If the operation results in a mu testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 7/6/2006 RU E M Hobbs Wireline. Set CIBP @ 7260'. Press tests Delaware I Sand from 7122' - 7136' w/2 JSPF, 28 holes. Pumped 100 7/10/2006 RU BJ Services. Tested treating lines to 5000 psi. Set ki 7122' - 7136' w/112,787 gal PW 10,000# 14/30 Lite Prop. 7/11/2006 Tagged fill @ 7261'. Cleaned out fill and tagged CIBP @ 7/12/2006 RIH w/2 7/8" J-55 tubing, seating nipple @ 7171'. PU public BLM NATIONWIDE BOND #NM2634. (CHK PN 891309) 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) LINDA GOOD Signature Linda Linda Look	ace locations and measured and tro. on file with BLM/BIA. Requiliple completion or recompletion all requirements, including reclar and case & CIBP to 3000 psi, O 10 gal 7 1/2% HCL acid. Ils to 3000 psi. Set pop-off to 20 7181'. Circ hole clean for 2 20 ymp 2 1/2" x 1-3/4" x 20', pto Title PERMITTING AGE	nue vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has K. RIH w/3 1/8" slick gun, perf wellbore in 3000 psi. Frac'd Delaware I Sand from ACCEPTED FOR RECOR thrs w/foam unit. AUG 4 2006 LES BABYAK PETROLEUM ENGINEER CNT 07/18/2006

which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.