Submit 3 Copies To Appropriate District Office State of New Mexico District I Idea State 1625 N. French Dr., Hobbs, NM 87240 Energy, Minerals and Natural Resources District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Sundry Notices And Reports ON Wells (Do Not USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Other 1. Type of Well: Other 2. Name of Operator Marathon 0il Company 3. Address of Operator P.0. Box 3487 Houston, TX 77253-3487	Form C-103 May 27, 2004 WELL API NO. <u>30-025-37754</u> 5. Indicate Type of Lease STATE \boxed{X} FEE $$ 6. State Oil & Gas Lease No. A-2614 7. Lease Name or Unit Agreement Name: McDonald State A/C 1-15 8. Well Number <u>1</u> 9. OGRID Number <u>1</u> 10. Pool name or Wildcat Wildcat Grayburg		
 4. Well Location Unit Letter <u>F</u>: <u>1650</u> feet from the <u>NORTH</u> line and <u>Section</u> <u>Section</u> <u>15</u> Township <u>22S</u> Range <u>36E</u> <u>11. Elevation</u> (<i>Show whether DR, RKB, RT, GR, 3543'</i> Pit or Below-grade Tank Application <u>or Closure</u> <u>Pit type</u> <u>Depth to Groundwater</u> <u>Distance from nearest fresh water well</u> <u>Pit Liner Thickness:</u> <u>mil</u> <u>Below-Grade Tank: Volume</u> <u>Dobls; Construe</u> 	NMPM County LEA etc.)		
12. Check Appropriate Box to Indicate Nature of Notice NOTICE OF INTENTION TO: SL PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: OTHER: OTHER:			
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Marathon Oil Company has completed operations to drill, set, and test the production casing string in the McDonald State A/C 1 - 15 No. 1 well. Marathon proposes to go to complete the well in the Grayburg formation. Please see attachment for details of work done and timeline for production casing.			
· · · · · · · · · · · · · · · · · · ·	dge and belief. I further certify that any pit or below- nit or an (attached) alternative OCD-approved plan mpliance Rep DATE 07/31/2006 cekendrix@marathonoil.com ETRULEUM ENGRAPHICE No. 713-296-2096		

AUG 2 2 2006

DATE _

For State Use Only		
APPROVED BY	TITLE	
Conditions of Approval if any		_

MIRO IL	ω <u>υ ι</u>	_	
Conditions	of Appr	oval, if	any:

McDonald State A/C 1 – 15 No. 1 Drill, Set, & Test Production Casing

04/09/2006	RIH w/ Bit & BHA. Drill out cement & shoe f/ 1200' to 1255'.Drill & survey 7 7/8" open hole from 1255' to 2,225'.		
04/10/2006	Drill & survey $7/78$ " open hole f/ 2,225' to 3,445'.		
04/11/2006	Drill & survey 7 7/8" open hole $f/2,225$ to $3,445$.		
04/12/2006	Drill & survey 7 7/8" open hole f/ $4,017$ to $4,605$ '.		
04/13/2006	Drill & survey 7 7/8" open hole f/ 4,605' to 4,759'. Stuck drill pipe. Worked pipe free.		
04/13/2000	Pumped high viscosity pill. POOH f/ bit change. Hole taking mud. Mixed and pump 250 LCM pill. Start IH / bit & BHA.		
04/14/2006	RIH t/ 976' pump 80 bbl LCM pill. Cont. in hole t/ 2,900'. Pump 40 bbl LCM pill & circ.		
0	Cont in hole t/ 4,300'. Pump 40 bbl LCM pill and circ. Cont. in hole t/ 4,650'. Wash &		
	ream f/ 4,650' to 4,759'. Drill f/ 4,759' to 4,848'. Repair to gearbox. Lost returns, regain		
	returns w/ LCM.		
04/15/2006	Drill f/ 4,848' to 4,942' losing partial returns. Switch mud pumps. Drill f/ 4,492 to 5,005		
	losing partial returns. POOH t/ 4,000'. Circ. @ low spm, Mixing LCM, and hauling brine		
	for volume.		
04/16/2006	Circulate, Mix LCM, Haul brine for volume. Drill f/ 5,005' to 5,440'.		
04/17/2006	Drill f/ 5,440' to 5,671'. Circ. & spot 80 bbl high viscosity pill.		
04/18/2006	Spot 40 bbl high viscosity pill. POOH w/ bit & BHA. Rig up Halliburton loggers. Run		
	triple combo logs to 5,662'. Change out rams to 5 1/2".		
04/19/2006	RU Bull Roger casing crew & run 5 1/2", J-55, 15.5 # LT &C casing to 5664' as follows:		
	Quantity Item Top Bottom Length		
	106 jts 5 ¹ / ₂ " casing 0 4397.25 4397.25'		
	1 DV tool 4397.25 4399.35 2.10'		
	30 jts 5 1/2" casing 4399.35 5640.41 1241.06'		
	1 Float collar 5640.41 5641.53 1.2'		
	1 5 ¹ / ₂ " sub5641.53 5662.46 20.93'		
	1 Float Shoe 5662.46 5663.66 1.20'		
04/20/2006	RU Halliburton Cementers. Pump 1 st stage 12 bbl Super flush 10, 300 sx Premium Plus,		
	Density 15.60, Yield 1.19 cuft/ sk, water mix 5.15 gal/ sk, displaced w/ 134 bbls brine,		
	bumped plug w/ 500 psi over, release w/ floats holding. Circ. 117 sks cmt to pits through		
	DV tool. Pump 2 nd stage, 12 bbls Super Flush, pump lead cmt 780 sks Interfill C,		
	Density 11.8, Yield 2.52 cuft/sk, Water mix 14.65 gal/sk; pumped tail 600 sks Premium		
	Plus, Density 15.6, Yield 1.19, Water mix 5.15 gal/sk, dropped plug, displaced w/ 104		
	bbls fresh water, bumped plug w/ 1500 psi. close DV tool no returns to pit. ND BOP, set slips w/ 50K weight. NU well head and test wellhead. RD drilling rig.		
07/24/2006	MI RU PU. RU Reverse Unit. St pipe racks. RIH w/ 4 ³ / ₄ " bit, 5 ¹ / ₂ " casing scraper, and		
0112412000	142 jts 2 7/8" tbg. Tag PBTD @ 4386'. PUH to 4226' w/ 137 jts in hole. SI well.		
	$142 \text{ Jis } 2 \text{ Ho} \text{ tog. } 142 \text{ Jis } 1010 \text{ e} 4300 \cdot 1011 \text{ to } 4220 \text{ w} \text{ F} 57 \text{ Jis in noise. St went}$		
07/25/2006	Circulate hole clean. RU McClaskey aicd truck. Spot 20 bbls 7 1/2% HCL acid f/ 3386' &		
0112012000	4226'. POOH w/ tbg.		
07/26/2006	RU Baker Atlas wireline. Ran Gamma Ray, CCL, & Radial Cement Bond log w/ 0 psi.		
	Repeat logs w/ 1000 psi on casing. Top of cement @ 1006' f/ surface. Pressure test BOP,		
	Blind rams and casing to 2600 for 30 minutes. Held Pressure.		