UNITEDSTATES DEPARTMENT OF THE INTERIOR BUDEAU OF LAND MANAGEMENT

FORMAPPROVED OM B No. 1004-0137 Expires: March 31, 2007

Name

(1919

	BUREATO OF	LIND	MANAGEMEN	11	TAND
SUNDRY	NOTICES	AND	REPORTS	ON	WEOGD-HOB
mat 41	ain fauun fau		. الأسلم ما مامم		

S5. Lease Serial No. LC - 032096(b)

so not use this form for proposals to unit of to re-enter an	6. If Indian, Allottee or Tribe
abandoned well. Use Form 3160-3 (APD) for such proposals.	

abandoned we	ell. Use Form 3160-	·3 (APD) for such pro	oposals.				
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well OilWell	8. Well Name and No. East Blinebry Drinkard Unit No. 17 9. API Well No. 30-025-06478 10. Field and Pool, or Exploratory Area Blinebry Oil & Gas (06660); Drinkard						
2. Name of Operator Apache Corporation							
3a. Address6120 South Yale, Suite 1							
4. Location of Well (Footage, Se-							
660' FSL & 1980' FEL, So 330	11. County or Parish, State Lea County New Mexico						
12. CHECK AI	PPROPRIATE BOX(ES	S)TO INDICATE NATUR	RE OF NOTICE, R	EPORT, OR OTHER DATA			
TYPEOF SUBMISSION	TYPEOF ACTION						
X Notice of Intent Subsequent Report	Acidize AlterCasing Casing Repair	Deepen FractureTreat New Construction	Production (State Reclamation Recomplete	Water Shut-Off Well Integrity Other			

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plugand Abandon

_ Plug Back

Pursuant to NMOCD Order No. F-12394

- 1. MIRU.
- 2. Clean out well to PBTD.

Final Abandonment Notice

- 3. Isolate and acidize Drinkard.
- 4. Isolate and acidize Blinebry.
- 5. RIH with injection tubing and packer.
- 6. Notify NMOCD and BLM offices prior to pressure test casing per regulations BABYAK

☐ Change Plans

X Convert to Injection

- 7. Set up surface equipment.
- 8. Begin injection.



☐ Temporarily Abandon

→ Water Disposal

I hereby certify that the foregoing is true and correct Name (Printed/Typed) Elaine Linton Title **Engineering Technician** 06/16/2006 THIS SPACE MOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant hold legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.