

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007**SUNDRY NOTICES AND REPORTS ON WELLS****Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.****SUBMIT IN TRIPLICATE- Other instructions on reverse side.**1. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator **Seely Oil Company**3a. Address
815 W. 10th St., Ft. Worth, TX 761023b. Phone No. (include area code)
817-332-1377

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**660' FSL & 1980' FWL U/L N
Sec. 11-T18S-R33E**

5. Lease Serial No.

NM 30398

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
Caviness Federal 2

9. API Well No.

30-025-2942810. Field and Pool, or Exploratory Area
Mescalero Escarpe; Bone Spring

11. County or Parish, State

Lea County, New Mexico**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION


TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☒ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Seely Oil Company acquired the subject well from EOG Resources Inc. effective 1/1/2005. A Queen test was drilled offsetting this well to the west. Seely respectfully requests permission to perform a MIT to test the csg and leave the well temporarily abandoned for one (1) year to evaluate the potential in the area. A CIBP is set above the Bone Spring perforations.

**APPROVAL SUBJECT TO
GENERAL REQUIREMENTS
AND SPECIAL STIPULATIONS
ATTACHED**



14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

David L. HendersonTitle **Executive V-P**

Signature

Date

08/11/2006**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

PE

Date

8/22/06

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

CFO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GWW

SUNDRY NOTICE SPECIAL STIPULATIONS

1. Operator must file a Sundry notice showing change of operator.
2. Operator must file a Subsequent Report showing that a CIBP is set a maximum of 50' above the Bone Spring perforations.