

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

|   |
|---|
| WELL API NO.<br>30-025-20214  |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>OG6014  |
| 7. Lease Name or Unit Agreement Name<br>MESA QUEEN UNIT   |
| 8. Well No.<br>12   |
| 9. Pool name or Wildcat   |

|   |  |
|---|--|
| SUNDRY NOTICES AND REPORTS ON WELLS<br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)                  |  |
| 1. Type of Well:<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>   |  |
| 2. Name of Operator<br>XERIC OIL & GAS CORPORATION  |  |
| 3. Address of Operator<br>P.O. BOX 352 MIDLAND TX 79702   |  |
| 4. Well Location<br>Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line<br>Section <u>17</u> Township <u>16S</u> Range <u>32E</u> NMMPM <u>LEA</u> County |  |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)  |  |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operation (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-31-03  
SPOT 25 SKS 3400' WOC & TAG @ 2947'  
PERF @ 1300' SQUEEZE 25 SKS WOC & TAG @ 1090'  
8-1-03  
PERF @ 600 SQUEEZE 50 SKS WOC & TAG @ 160'  
SPOT 20 SKS 100' TO SURFACE

CIRCULATE MUD  
INSTALL P&A MARKER

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeff Kester TITLE \_\_\_\_\_ DATE 8-1-03

TYPE OR PRINT NAME JEFF KESTER TELEPHONE NO. 915-547-2926

(This space for State Use)

APPROVED BY Gary W. Wink TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

OIL FIELD REPRESENTATIVE II/STAFF MANAGER

AUG 14 2003