State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-31429	
DISTRICT II	2 1 3,		5. Indicate Type of Lease	-
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreem	ient Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			South Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE ".	APPLICATION FOR PERMIT" (Form C-	101) for such proposals.)	Section 4	
1. Type of Well: Oil Well X	Gas Well Other		8. Well No. 236	
2. Name of Operator			9. OGRID No. 157984	· · · · · · · · · · · · · · · · · · ·
Occidental Permian Ltd.			137701	
3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323			
4. Well Location				
Unit Letter K : 1403	Feet From The South	1746 Fee	t From The West	Line -
Section 4	Township 19	Range 38-F	E NMPM	Lea County
	11. Elevation (Show whether DF, Ri	KB, RT GR, etc.)	V////////	
	3619' KB			
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Ma	terial	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INT			SEQUENT REPORT OF	= :
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPI		BANDONMENT
PULL OR ALTER CASING	Multiple Completion	·		DAINDONNIE!!
	Wattiple Completion	CASING TEST AND CEMEN		
OTHER:		OTHER: Plug back/0	Open additional perfs/Stim	X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
proposed work) ozza wezza 1103	To Manaple Completions. Attach v	ventorie diagram of proposed c	completion of recompletion.	T Q.
1. RUPU & RU? Pull out of hole w/s	bg & ESP equipment.	•	00)()
2. Clean out to 4292'. Circ well clean. Set CR @4210'.				
3. Pump 90 bbl fresh water thru CICR @4120 w/no circ above CR. 4. Mix & pump 100 sx prem plus w/2% Cal Chloride cement. Flush to end of tbg. 5. Drill out from 4180'- 4210'. Circ Clean. 6. Perforate w/4 JSPF @4089-4098', 4107-4113', 4180-4208'. (184 holes) 7. Acidize perfs 4089-4208' with 2000 gal 15% acid in four settings. Swab fluid out of well. Recovered 200 bbl.				
4. Mix & pump 100 sx prem plus w/2% Cal Chloride cement. Flush to end of tbg.				
5. Drill out from 4180'- 4210'. Circ Clean. 6. Perforate w// ISPE @4080 4008' 4107 4113' 4180 4208' (184 hales)				
6. Perforate w/4 JSPF @4089-4098', 4107-4113', 4180-4208'. (184 holes) 7. Acidize perfs 4089-4208' with 2000 gal 15% acid in four settings. Swab fluid out of well. Recovered 200 bbl.				
8. Pump 200 gal of 6490 mixed with 100 bbl of fresh water. Flush with 500 bbl of fresh water.				
9. Ran back in hole w/126 jts of new 2-7/8" tbg and ESP equipment. Intake set @4045'				
10. RDPU & RU. Clean location. RUPU 07/06/06 RDPU 07/28/06				
		· · · · · · · · · · · · · · · · · · ·	01/20/00	
I hereby certify that the information above is constructed or	true and complete to the best of my know	ledge and belief. I further certify	that any pit or below-grade tank ha	as been/will be
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved				
plan				
SIGNATURE New Long	-Urohmin	TITLE Administrative	Associate DATE	08/08/2006
TYPE OR PRINT NAME Mendy A. J	ohnson E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO.	806-592-6280
For State Use Only				
APPROVED BY Mis //	Tilleanna	OC DISTRICT SUPER	NSOR/GENERAL MAN	0600 A P 0000

CONDITIONS OF APPROVAL IF ANY: