

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No. 1004-0135
Expires: January 31, 2004

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

BTA Oil Producers

3a. Address

104 . Pecos, Midland, TX 79701

3b. Phone No. (include area code)

(432) 682-3753

4. Location of Well (Footage, Sec., T. R., M., or Survey Description)

660' FSL & 1980' FEL SW/SE UL -O-
Sec. 18, 23S-34E

5. Lease Serial No.

LC1065194

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

NMNM104029

8. Well Name and No.

Bell Lake, 7909 JV-P No. 2

9. API Well No.

30-025-34827

10. Field and Pool, or Exploratory Area

Wildcat Upper Penn

11. County or Parish, State

Lea County., NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☒ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BTA Oil Producers proposes to plug back and test the Delaware Y Sand as follows:

. MIRU. ND WH. NU BOP.

. Rel pkr & POH.

. RIH w/CIBP for 5" 18# liner to 11800'. Cap w/40' cmt.

. RIH w/CIBP for 7" 29# casing to 11300'. Cap w/40' cmt.

. Run GR-CCL log from 8400-7900'.

. Perf 8243-8257'.

. RIH w/tbg & pkr. Spot 200 gal 7-1/2% HCl acid.

. Raise pkr & set @ +/- 8100'. Press test to 500 psi.

. Breakdown perfs and swab well down to packer to evaluate.

0. If acid and frac are warranted, frac w/21500 gals Lightning 3000 carrying 34500 # sand.

1. Flow back and swab to evaluate.

APPROVED

AUG 17 2006

LES BABYAK
PETROLEUM ENGINEER

4. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Pam Inskeep

Signature

Title

Regulatory Administrator

Date

07/31/2006

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by (Signature)

Name

(Printed/Typed)

Title

Office

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(continued on next page)