

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-025-11619
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: South Langlie FAL Unit
8. Well No. 13-W1W
9. Pool name or Wildcat Langlie Mathis

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☐ Gas Well ☒ Other W1W	
2. Name of Operator Smith & Marrs Inc	
3. Address of Operator Box 863 Kermit, TX. 79745	
4. Well Location Unit Letter A : 990 feet from the EAST line and 990 feet from the North line Section 18 Township 25S Range 37E NMPM County Lea	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Set C18P@ 3100
Spot 25x46 @ 3100-2900
Spot 25x45 @ 2630-2500
Spot 25x45 @ 1630-1430
Perf@ 351'
Squeeze 40 5x5 @ 351-251' & tag
Spot 10 5x5 @ 50' to surface

**THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.**

INSTALL DRY Hole Marker - Cir 10" MUD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE **[Signature]** TITLE **Pres** DATE **9-6-06**

Type or print name **Rickey Smith** Telephone No. **432-586-3076**
(this space for State use)

APPROVED BY **[Signature]** DATE **SEP 14 2006**
Conditions of approval, if any: **OG FIELD REPRESENTATIVE II/STAFF MANAGER**

LOG ZERO = 7' ABOVE G.L.

GL = 3106'

8 5/8", 24# to 301'
(Cm'd. w/ 200 SYS. WITH
SURFACE RETURNS)

HOLE SIZES
13 3/4", 0 - 301'
7 7/8", 301 - 3320'

5 1/2", 14# to 3230'
(Cm'd. w/ 200 SYS. OUT SHOE
+ 200 SYS. OUT 2 STAGE
TOOL AT 1580')

SOUTH LAGLIE JAL UNIT, #13-WIW
(Formerly DALPORT'S, WINTERS 'E', #2)
JALMAT (OIL) FIELD
LEA CO., NEW MEXICO

CRC 11/6/76

1580', 2 STAGE TOOL

TD - 3230'