Submit 3 Copies To Appropriate District Office	State of Nev		Form C-103 May 27, 2004		
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and		WELL API NO. 30-025-01432	Wiay 27, 2004	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVAT	ION DIVISION	5. Indicate Type of Le	2256	
District III	1220 South St.	Francis Dr.	STATE	FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505		6. State Oil & Gas Lea		
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-2148		
SUNDRY NOTI (DO NOT USE THIS FORM FOR PROPOS	CES AND REPORTS ON W.		7. Lease Name or Uni	t Agreement Name	
DIFFERENT RESERVOIR. USE "APPLIC	ATION FOR PERMIT" (FORM C-	101) FOR SUCH	Shahara State Unit		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number		
7.	Cus wen Z cuter		5		
2. Name of Operator			9. OGRID Number 187940	•	
AROC (Texas), Inc. 3. Address of Operator			10. Pool name or Wild	lcat	
110 Cypress Station Dr., #220 Houston, TX 77090			Maljamar Grayburg		
4. Well Location	VEC 11				
Unit LetterL:	1980feet from the\$	South line and	660feet from the	Westline	
Section 16	Township 1	7S Range 33E	NMPM Lea	County	
A THE LOW THE PARTY OF	11. Elevation (Show whether 4190' GR	er DR, RKB, RT, GR, etc.,			
Pit or Below-grade Tank Application O				ı	
Pit typeDepth to Groundwa		fresh water well Dis		ater	
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	onstruction Material		
12. Check A	Appropriate Box to Indicate	ate Nature of Notice,	Report or Other Dat	a .	
NOTICE OF IN	TENTION TO:	l SUB	SEQUENT REPO	RT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING: ☐					
TEMPORARILY ABANDON			LLING OPNS. PA	ND A	
PULL OR ALTER CASING	MULTIPLE COMPL				
OTHER:	Г	OTHER:			
13. Describe proposed or comp	leted operations. (Clearly sta	te all pertinent details, an	d give pertinent dates, in	cluding estimated date	
	ork). SEE RULE 1103. For M	Multiple Completions: At	tach wellbore diagram o	f proposed completion	
or recompletion.			· · · · · · · · · · · · · · · · · · ·	GYPPD 1100#	
Perfs 4178'-4430'. OH 44:	58'-4550'. 2-3/8" tbg to 4130	'. Casing will not pass M	II. No tbg/csg commun	ication. SITP 1100#.	
1. Sqz perfs down tbg w/25 sxs cement. 2. MIRU PU. Circulate hole with mud. Release packer. Pull out of hole. 3. Rig up ELU. Set cast iron bridge at 4150'. 4. Trip in hole with tbg. Spot desxs cement plug on cast iron bridge plug. 35/5% // 5/07/180'. Tag. 5. Pull up to 2800'. (Top of Yates 2750'). Spot 25 sxs plug from 2620'-2800'. Tag. 6. Pull up to 1580'. Top of Salt 1530'). Spot 25 sxs plug from 1350'-1580'. PERF 352 7. Pull up to 420'. (8-5/8" at 370'). Spot 25 sxs plug from 240'-420'. Tag. PERF 352					
3. Rig up ELU. Set cast iron bridge at 4150'.					
4. Trip in hole with t	bg. Spot sxs cement plug	on cast iron bridge plug	-35 CEMON SPOTTE	D M.	
5. Pull up to 2800'.	(Top of Yates 2750'). Spot 2	5 sxs plug from 2620'-28	00'. Tag.	1250	
6. Pull up to 1580'.	Top of Salt 1530'). Spot 25 s	xs plug from 1350'-1580	'- PERFIT SOZ 50 B	acelle 11 4 240	
7. Pull up to 420'. (8	3-5/8" at 370'). Spot 25 sxs p w ground level. Weld on plat	lug from 240'-420'. Tag	- Perf. 4502 11 "	Hobbs	
8. Cut casing 3' belo	w ground level. Weld on plat	te. 5700 10510 0 30	KNOROD	OCD	
THE ALL ASSAULT				1	
THE OIL CONSER	VATION DIVISION ML	JST		2. 2. 2. 4.	
BE NOTIFIED 24	HOURS PRIOR TO TH				
BEGINNING OF PL	UGGING OPERATION	NS.		į	
I hereby certify that the information	above is true and complete to	the best of my knowledg			
grade tank has been/will be constructed or	0				
SIGNATURE Clarita	X	LEMgr. Production A		DATE9/19/2006	
Type or print name For State Use Only	E-mail:	address: Juanita@sber	nergy.com Telephone N	SEP1-237-92006	
9/	1.) i.h	v D	<u>-</u> .	A COND	
APPROVED BY: \(\square\) Conditions of Approval (if axy):	Wenge TI	JEHELD REPRESENTAT	IVE ILISTATE MANAR	姓上	