Submit 3 Copies To Appropriate District State of New Mexico	Form C-103		
District I Energy, Minerals and Natural Resources	May 27, 2004		
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Ave., Artesia NM 88210 OIL CONSERVATION DIVISION	WELL API NO.: 30 025 29474		
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION   District III 1220 South St. Francis Dr.	5. Indicate	Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		TE X FEE	
District IV Santa Fe, INIVI 87505	6. State Oil B 9560	l & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease N	ame or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	N.M. "BG" St. NCT-1 8. Well Number: 8		
Type of wen. On wen A Gas wen Ould		mber: 8	
2. Name of Operator: CrownQuest Operating, LLC	9. OGRID Number: 213190		
3. Address of Operator:	10. Pool na	name or Wildcat	
c/o P.O. Box 953, Midland, TX 79702	Saunde	rs Permo Upper Penn	
4. Well Location			
Unit Letter A :660feet from theNorth line and455f	eet from the	Eastline	
Section 14 Township 14S Range 33E		Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	.): 4193 '		
Pit or Below-grade Tank Application 🗌 or Closure 🗌	<u></u>	<u> - Antonio de la construcció de la cons</u>	
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUE   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR   TEMPORARILY ABANDON X CHANGE PLANS COMMENCE DR   PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN   OTHER: OTHER: OTHER:   13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	RK RLLING OPNS IT JOB	nt dates, including estimated date	
Proposed T/A procedure: Notify NMOCD district office. Move in and rig up wireline. RIH w/4.75" gauge ring to 9810'. Run in hole w/10,000 psi CIBP and set 9750'. Top of cement is circulated to surface. Run in hole w/dump bailer and dump 20' of cement on top of CIBP. Rig down wireline and rig up pump truck. Load & test CIBP to 500 psi for 30 minutes.		SEP MARK	
I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines X, a general permit SIGNATURE	or an (attached) a	alternative OCD-approved plan □. DATE7-21-06 32 684-6381 SEP 2 6 2006	
	IVSTAFF MAX	NAGEN	

i