

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-33388
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-5467
7. Lease Name or Unit Agreement Name Pawnee APW State
8. Well Number 1
9. OGRID Number 025575
10. Pool name or Wildcat Wildcat Grayburg, Wildcat San Andres Reeves; Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
105 S. 4th Street, Artesia, NM 88210

4. Well Location
Unit Letter A : 660 feet from the North line and 660 feet from the East line
Section 20 Township 18S Range 35E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3932' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Steel Depth to Groundwater N/A Distance from nearest fresh water well N/A Distance from nearest surface water N/A

Pit Liner Thickness: N/A mil Below-Grade Tank: Volume N/A bbls; Construction Material N/A

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P & A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Propose to Plug & Abandon as follows:

- 1) MIRU plugging equipment. TOOH w/production equipment.
- 2) Circulate hole w/mud. Spot 100' plug 5130-5030'. Pull up and spot 100' plug 4730-4630'. Pull up and spot 100' plug 4360-4260'.
- 3) Spot 100' plug across DV tool 3850-3750'. Spot 100' plug 3040-2700'. Spot 100' plug 1838-1738'. WOC and tag. **SPOT 100' PLUG F/400'-300'**
- 4) Perforate @ 60'. Circulate cement and spot plug 60' to surface.
- 5) Install marker and clean location.

(Proposed Schematic Attached)

**THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Stormi Davis TITLE Regulatory Compliance Technician DATE 9-25-06

Type or print name Stormi Davis E-mail address: stormid@ypcnm.com Telephone No. 505-748-1471

For State Use Only

APPROVED BY: Ray W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE SEP 27 2006

Conditions of Approval (if any):

Well Name: Pawnee "APW" State #1 Field: _____


Location: 660' FNL & 660' FEL Sec. 20-18S-35E Lea Co., NM

GL: 3932' Zero: _____ AGL: _____ KB: 3944'

Spud Date: 11-23-96 Completion Date: _____

Comments: _____

Casing Program	
Size/Wt/Grade/Conn	Depth Set
11 3/4" 42# H40 ST&C	1788'
5 1/2" 17# N80 & K55, 15.5#J55	6850'



SKETCH NOT TO SCALE

DATE: _____