

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505


WELL API NO. 30-025-36330
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> P
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	7. Lease Name or Unit Agreement Name Lou Wortham
2. Name of Operator Pecos Production Company	8. Well Number 8
3. Address of Operator 400 W. Illinois, Suite 1070, Midland, TX 79701	9. OGRID Number 215758
4. Well Location Unit Letter <u>D</u> : 330' feet from the <u>North</u> line and <u>990</u> ' feet from the <u>West</u> line Section <u>11</u> Township <u>22S</u> Range <u>37E</u> NMPM <u>Lea</u> County	10. Pool name or Wildcat Eunice, SA South / Penrose Skelly; GB
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3370' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: Spud Well & Set Surface Casing <input checked="" type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/12/03 - MIRU Capstar Drlg Rig # 6. Spud 12 1/4" hole @ 4:30 pm.
8/14/03 - TD 12 1/4" hole @ 1167'. Ran 8 5/8" 24# J-55 8rd csg & set csg @ 1164'. Cmt csg w/400 sxs Cl C, 4% gel, 1/4# cello, 2% CaCl followed by 250 sxs Cl C, 2% CaCl. Circ 61 sxs. WOC 18 hrs.
8/15/03 - NU BOP, test BOP & pipe rams & resume drlg 7 7/8" hole.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dora Bustamante TITLE Engineer Assist DATE 8/18/03

Type or print name Dora Bustamante E-mail address: dorab@pecosproduction.com Telephone No. 432-620-8480

(This space for State use)

APPROVED BY Larry W. Wink TITLE FIELD REPRESENTATIVE II / STAFF MANAGER DATE AUG 20 2003
Conditions of approval, if any: