New Mexico Oil Conservation Division, District I

1625 N. French Drive

Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Mobbs, NAI 88246

FORM APPROVED OMB No. 1004-0135

Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.						
					5. Lease Serial No. NM-015807 N/1-90584 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well					7. If Unit or CA/Agreement, Name and/or No.	
Oil Well X Gas Well Other					8. Well Name and No.	
2. Name of Operator					Holder Federal #1	
Yates Drilling Company					9. API Well No.	
3a. Address 3b. Phone No. (include area code)					30-005-10168	
105 S. 4th Str., Artesia, NM 88210 4. Location of Well (Footage, Sec.,T.,R.,M., OR Survey Description)			48-8463		10. Field and Pool, or Exploratory Area SE Chaves QN Gas Area Assoc	
4. Location of vveil (Foolage, Sec., F., K., M., OR Survey Description)					11. County or Parish, State	
660' FSL & 1980' FEL, Section 4-13S-31E					Chaves, NM	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R						
	MATE BOA(E6) TO	111010111211				
TYPE OF SUBMISSION	PE OF SUBMISSION TYPE OF ACTION					
	Acidize	Deepen	Ĺ	Production (S	Start/Resume)	Water Shut-Off
X Notice of Intent	Alter Casing	Fracture '	Γreat [Reclamation		Well Integrity
	Casing Repair	New Cor	struction	Recomplete		Other
Subsequent Report	Change Plans	Change Plans X Plug and Abandon Temporar		Temporarily .	Abandon	
Final Abandonment Notice Convert to Injection Plug Back Water Dispos					sal	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days. following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 1) Set CIBP @ 2565', spot cement 2515'-2565' 2) Circ hole with 10#/gal mud 3) Perforate 2 holes @ approx. 1100' (Top of Salt). Try to circulate water 4) Set retainer @1050' and squeeze cement to surface 5) Spot cement plug from 232'-332' across 8 5/8" casing shoe 6) Spot cement plug from 0-50' 7) Erect dry hole marker, remove all equipment and clean location.						
14. I hereby certify that the foregoing is true. Name (Printed/Typed) Karen J. Leishman	e and correct	Title	Operatio 9/26/200	ons Tech		
Signature Taxen	THIS SDACE	FOR FEDERAL				
Approved by /S/ DAVI	D R. GLAS	S		ROLEUM EN	GINEER Date	SEP 2 8 2006
Conditions of approval, if any, are attache certify that the applicant holds legal or ed which would entitle the applicant to conduct the applicant the applicant to conduct the applicant the app	quitable title to those rights i		Office	OF # I	ገ የተፈጠው ነበር መስመ	-m