

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-09868
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name BC.DICKINSON A1
8. Well Number 2
9. OGRID Number
10. Pool name or Wildcat Denton (Devonian)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Americo Energy Resources, LLC

3. Address of Operator

7575 San Felipe, Suite 200, Houston, TX 77063

4. Well Location

Unit Letter L : 2240 feet from the South line and 400 feet from the West line
Section 1 Township 15S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
GL3808'

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Proposed Remedial Work

Inform "OCD" before start working on the well.

- MIRU Service rig. Spot rig pump & tank, fill with kill fluid.
- Bleed off csg/tbg pressure. Displace kill fluid down 7" casing to kill the well, if necessary.
- N/D wellhead flange & N/U bop's.
- RU wire line, clear casing string to top of fish @7000' (perfs-12474-12562'). Pooh w/same.
- GIH with packer on work string. Set pkr at 7000', test casing string to 500 psi for 30 minutes.
- Pooh with BHA, lay down packer. Send the test results & C-130 form to OCD of NM.
- TIH with tubing string open ended. N/D & N/U.
- Rig down service rig and move out.
- Shut well in Pending well evaluation and AFE cost to clean up the well/put well back on production.
- P/A or T/A the well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE [Signature] TITLE Vice President - Operations DATE 10/2/06

Type or print name Oscar Nosrati

E-mail address: oscar.nosrati@americoenergy.com Telephone No. 713-984-9700

For State Use Only

APPROVED BY: [Signature] DATE _____

Conditions of Approval (if any):

OCD FIELD REPRESENTATIVE or STAFF MANAGER

OCT 05 2006

