## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION						
DISTRICT I 1220 Sou		th St. Francis Dr.		WELL API NO.		
1625 N. French Dr. , Hobbs, NM 88240	Santa I	Fe, NM 87505		30-025-2917	/3	
DISTRICT II		1	5. Indicate	Type of Lease		
1301 W. Grand Ave, Artesia, NM 88210	i			STATE X	FEE	
DISTRICT III	!		6. State Oil	l & Gas Lease No.		
1000 Rio Brazos Rd, Aztec, NM 87410	OTICES AND DEPORTS ON V	VELLC	7 Lease No	ame or Unit Agreeme	ant Nama	
SUNDRY NOTICES AND REPORTS ON WELLS				<del>-</del>	ent Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			l l	North Hobbs (G/SA) Unit Section 32		
1. Type of Well:			8. Well No			
Oil Well X	Gas Well Other			332		
2. Name of Operator			9. OGRID	No. 157984		
Occidental Permian Ltd						
3. Address of Operator	v 70222		10. Pool na	ime or Wildcat	Hobbs (G/SA)	
HCR 1 Box 90 Denver City, T.  4. Well Location	X 19323		1			
	Foot From The C (1	2250	Ford France The	<b>1</b> 77	• •	
Unit Letter J : 1550	Feet From The South		Feet From The	East	Line	
Section 32	Township 18-S	Range	38-E N	IMPM	Lea County	
	11. Elevation (Show whether DF	, RKB, RT GR, etc.)				
	3627' GL					
Pit or Below-grade Tank Application	or Closure					
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water						
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material						
2000, Constitution Waterian						
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING						
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT					BANDONMENT	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB						
Open additional peristacianze 2						
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any						
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion						
1. Pull ESP equipment.						
2. Pun hit & coroner to DDTD @4200?						
3. Run CNL/NGS/CCL log from PBTD to ±3250'.  4. Perforate hole @4075-80', 4118-22', 4128-32', 4160-70', 4180-88', with 180 decree spiral @2 ISBE						
4. Perforate note @4075-80', 4118-22', 4128-32', 4160-70', 4180-88' with 180 degree spiral @2 JSPF.						
5. Acid treat well with 1260 gal of 15% PAD HCL acid. 6. Run back in hole with tubing & ESP equipment.						
o. Run back in note with tubing & L	51 equipment.					
	1			No.		
	!			534®	₽ p	
	:				<u> </u>	
Thoroby comify that the info						
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or						
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved						
$\gamma$		plan				
SIGNATURE VULNOU	a ( I Althour	~ TITLE Administr	ative Associate	DATE	10/05/2006	
TYPE OR PRINT NAME Mendy A	Johnson E-mail address:	mendy_johnson@ox	***************************************	TELEPHONE NO	806-592-6280	
For State Use Only			- ILICTAFE A	MANAGEE	300-372*0280	
APPROVED BY Jayu. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER						
CONDITIONS OF APPROVAL IF ANY						
COMPANDIO OF AFFRUVAL IF ANY						