Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-005-20174
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u>	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C 10) FOR SUCH			
PROPOSALS.)			Cato San Andres 8. Well Number 84
1. Type of Well: Oil Well			·
2. Name of Operator UHC New Mexico Corp.	REOLINIES.		9. OGRID Number 183718
3. Address of Operator	ess of Operator		10. Pool name or Wildcat
P.O. Box 450, 303 W. Main, Ste.	300, Artesia, N.M. 88210		Cato San Andres
4. Well Location			
Unit Letter H: 1980 feet from the north line and 660 feet from the east line			
Section 14 Township 8S Range 30E NMPM Chavez County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application or Closure			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mi	Below-Grade Tank: Volume	bbls; Co	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐			
PULL OR ALTER CASING	<u></u>	CASING/CEMEN	
OTHER			_
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER:			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
06-28-06 MIRU. Latch onto sand line, came apart. RIH w/ spear & 13 jts. Shut dn. 06-29-06 Loaded csg, drop cable cutters. Got sand line out of hole. Put on BOP, RIH w/ fishing tool. Unable to fish out cable cutters.			
Shut dn.			
06-30-06 RIH w/ overshut & tbg, tag. Wash down to tag fish @ 3433'. Unable to fish out, POOH. Shut down.			
07-05-06 RIH w/ overshut & tbg, tag. Wash down to fish, unable to latch on. POOH, clean off tools, RIH, tag, wash down. Fished out			
cable cutting & pulled out two stands. Shut down. 07-06-06 POOH w/ tbg, tried three more trips, unable to latch onto fish. RIH w/ packer to 2800', set packer. Test csg @ 300psi, held			
Ok. Bleed off well, POOH w/ tbg, shut dn.			
07-07-06 RIH w/ mill shoe, collars & tbg to 3433', tag, started milling out to 3490'. Pulled out some cable & cable cutting, shut dn.			
07-10-06 RIH w/2 jts, tag, p/u power swivel. Started milling out from 3490' to 3492'. POOH, changed mill shoe, RIH, tag. Shut dn.			
07-11-06 Started drilling, couldn't pass through. POOH, changed shoe, RIH, tag @ 3492', couldn't pass through. RIH w/ overshut Tool complications hindered any more drilling. Shut down.			
07-12-06 POOH w/ tbg. Replaced shoe, RIH, tag @ 3496'. Ran another shoe, tag @ 3496'. Started wash down to TD @ 3655'.			
Circulate, clean, POOH v		, 20	Č
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-			
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .			
J R RE			
SIGNATURE	TI	TLE <u>Production</u>	1ecn PATE 21 20
Type or print name Ronnie	e Grado E-mail address:		Telephone No. 508-746-4448
			T 027 0 7096
APPROVED BY:			
APPROVED BY: Conditions of Approval (if any):	TITLE		
			