⁷ N.M. Oil Cons. Di	V-Dist. 2
Form 3160-5 UNITED STATES 1301 W. Grand	Avenuel FORM APPROVED
Form 3160-5 UNITED STATES (April 2004) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENTICSIA, NM 8	8210 OMB No. 1004-0135 Expires March 31, 2007
SUNDRY NOTICES AND REPORTS ON WELLS	5. Lease Serial No RECE 2008
Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name
	7. If Unit or CA/Agreement, Name and/or No.
SUBMIT IN TRIPLICATE - Other instructions on reverse side	153420
1. Type of Well Oil Well Gas Well Other	8. Well Name and No.
2. Name of Operator	Eddleman Federal #2
Yates Petroleum Corporation 3a Address 3b Phone No. (include area code)	9. API Well No. 30-005-61369
3a. Address 3b. Phone No. (include area code, 105 S. 4th Str., Artesia, NM 88210 505-748-1471	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)	Pecos Slope Abo
	11. County or Parish, State
1980'FNL & 1980'FEL of Section 9-T7S-R22E (Unit G, SWNE)	Chaves County, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF	NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
Acidize Deepen	Production (Start/Resume) Water Shut-Off
X Notice of Intent Alter Casing Fracture Treat	Reclamation Well Integrity
Casing Repair New Construction	Recomplete Other
Change Plans X Plug and Abandon	Temporarily Abandon
Final Abandonment Notice Convert to Injection Plug Back	Water Disposal
13. Describe Proposed of Completed Operation (clearly state all pertinent details, including estimated starting date of any prost if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vera Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required sub following completion of the involved operations. If the operation results in a multiple completion or recompletion in a netsting has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamatic determined that the site is ready for final inspection.)	tical depths of all pertinent markers and zones. sequent reports shall be filed within 30 days. w interval, a Form 3160-4 shall begiled once
Yates Petroleum Corporation plans to plug and abandon this well as follows	NMOCD 4
 MIRU all safety equipment as needed. No casing recovery will be attemp Tag CIBP at 3100'. If 35' cement on top continue to Step 3, if there is no puts a plug over the Pennsylvanian. Set a CIBP at 2822' with 35' cement on top. This puts a plug over the Ab Perforate at 1047' and spot a 35 sx Class "C" cement plug from 947'-104' casing shoe, inside and outside the casing. WOC and tag plug. Perforate at 60' and circulate a 15 sx Class "C" cement plug from 60' up t Remove all surface equipment and weld dry hole marker per regulations. 	cement, dump 35' cement on top. This o. 7'. This puts a 100' plug across the surface
NOTE: Yates Petroleum Corporation will use steel pits and no earth pits	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Tina Huerta Title	ory Compliance Supervisor
	ber 18, 2006
THIS SPACE FOR FEDERAL OR STATE OF	EICE USE
Approved by /S/ ALEXIS C. SWOBODA	KOLEUM ENGINEEN SEP 2 0 2006
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certity that the applicant holds legal or equitable tille to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.	
	willbully to make to any department or agency of the United

?



