

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-07364
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: North Hobbs G/SA Unit
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well Number 241
2. Name of Operator Occidental Permian Limited Partnership		9. OGRID Number 157984
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294		10. Pool name or Wildcat Hobbs; Grayburg - San Andres
4. Well Location Unit Letter <u>N</u> : <u>330</u> feet from the <u>South</u> line and <u>2310</u> feet from the <u>West</u> line Section <u>19</u> Township <u>18-S</u> Range <u>38-E</u> NMPM County <u>Lea</u>		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3661' DF		
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐


SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Temporarily Abandon Well ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This Approval of Temporary 9/20/11
Abandonment Expires

See Attachment



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐


SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 10/10/06
Type or print name Mark Stephens E-mail address: Mark_Stephens@oxy.com Telephone No. (713) 366-5158

For State Use Only

APPROVED BY Laurel W. Winkler TITLE FIELD REPRESENTATIVE II/STAFF MANAGER DATE OCT 17 2006
Conditions of Approval, if any:

9/15/06 - 9/20/06:

MI x RU. NU BOP. POOH with production equipment. RIH with bit x 5-1/2" casing scraper to 4176'. RU Schlumberger WL and set 5-1/2" CIBP at 4155' and cap with 20' cement. Set second 5-1/2" CIBP at 4050' and cap with 20' cement. Set 7" CIBP at 3900' and cap with 20' cement. Circulate hole with 160 bbls packer fluid. Test CIBP to 1000 psi. Pressure test casing to 620 psi x 30 min. (held). ND BOP. RD x MO. Well is temporarily abandoned.



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

Oxy Permead
NHu 19-241

BR 2221