

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

OXY USA WTP Limited Partnership

192463

3a. Address

P.O. Box 50250, Midland, TX 79710-0250

3b. Phone No. (include area code)

432-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1080 FSL 1300 FWL SWSW(M) Sec 11 T18S R28E

5. Lease Serial No.

NM-54184

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No.

OXY Longnose #1

Federal

9. API Well No.

30-015-34685

10. Field and Pool, or Exploratory Area

Undsg. Empire Morrow, South

11. County or Parish, State

Eddy NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

TD-10955' PBTB-10515' Perfs-9904-9927'  
Perfs-10622-10868' CIBP @ 10550' w/ 4sx cmt

13-3/8" 48# csg @ 475' w/ 500sx, 17-1/2" hole, TOC-Surf-Circ  
9-5/8" 36# csg @ 3000' w/ 1200sx, 12-1/4" hole, TOC-Surf-Circ  
5-1/2" 17# csg @ 10955' w/ 1510sx, 8-3/4" hole, TOC-1920'-TS  
DV Tool @ 7980', 1<sup>st</sup> w/660sx-7975'-Circ, 2<sup>nd</sup> w/850sx-1920'-TS

- 40sx
1. RIH & Set CIBP @ 9855', dump 5sx cmt to 9820' TAG
  2. M&P 25sx cmt @ 8030-7930' 7830' Top of Wellcamp/DV Tool
  3. M&P 25sx cmt @ 6500-6400' 6050-5950' ← per David Stewart
  4. M&P 25sx cmt @ 3050-2950' TAG
  5. Cut & Pull 5-1/2" csg @ +/- 1950'
  6. M&P 35sx cmt @ 2000-1900' TAG
  7. M&P 50sx cmt @ 525-425' TAG
  8. M&P 25sx cmt surface plug
- 10# MLF between plugs

Accepted for record  
NMOCD

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

David Stewart

Title

Sr. Regulatory Analyst

Date

10/3/06

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Office

Date

OCT 11 2006

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**OXY USA WTP LP - Proposed**  
**OXY Longnose Federal #1**  
**API No. 30-015-34685**

**25sx Surface**

**50sx @ 525-425'**

**35sx @ 2000-1900'WOC-Tag**


**25sx @ 3050-2950'**

**25sx @ 6500-6400'**

**25sx @ 8030-7930**

**CIBP @ 9855 w/ 5sx**

9/18/06-CIBP @ 10550' w/4sx cmt



17-1/2" hole @ 475'  
13-3/8" csg @ 475'  
w/500sx-TOC-Surf-Circ

**Cut & pull +/- 1950' 5-1/2" csg**

12-1/4" hole @ 3000'  
9-5/8" csg @ 3000'  
w/1200sx-TOC-Surf-Circ

**Accepted for record**  
**NMOCD**

8-3/4" hole @ 10955'  
5-1/2" csg @ 10955'  
DV Tool @ 7980'  
1st w/660sx-TOC-7975'-Circ  
2nd w/850sx-TOC-1920'-TS

Perfs @ 9904-9927'

Perfs @ 10622-10868'

TD-10955'