Form 3160-5 (April2004)	UNITEDSTATES DEPARTMENT OF THE INTERIC	R OCD-HC	BBS FORMAPPROVED OM B No. 1004-0137 Expires: March 31, 2007						
J	BUREAU OF LAND MANAGEMENT	[5. Lease Serial No.						
SUNDRY	NOTICES AND REPORTS	ON WELLS	NM 0557686						
Do not use the abandoned we	is form for proposals to drill or ell. Use Form 3160 - 3 (APD) for s	to re-enter an such proposals.	6. If Indian, Allottee or Tribe Name						
	PLICATE - Other instructions of	on reverse side.	7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well	8. Well Name and No.								
2. Name of Operator	SEMU Permian Well #38								
ConocoPhillips Company			9. API Well No.						
3a. Address 4001 Penbrook Street Oc		No.(include area code))368-1667	30-025-06254 10. Field and Pool, or Exploratory Area						
	c., T., R., M., or Survey Description)	1007	Skaggs; Grayburg						
660' FNL & 1980' FEL Sec. 24, T-20-S, R-37-E	11. County or Parish, State Lea New Mexico								
12. CHECK AI	PROPRIATE BOX(ES)TO INDICATE	E NATURE OF NOTICE. R							
TYPEOF SUBMISSION									
		TYPEOF ACTION							
Noticeof Intent	Acidize Deepen	Production (Sta	rt/Resume) L Water Shut-Off						
X Subsequent Report		struction Recomplete	X OtherRepair						
	Change Plans Plugand								
Final Abandonment Notice	Convert to Injection PlugBac		Failure						
Attach the Bond under which t following completion of the inv	he work will be performed or provide the Bond i volved operations. If the operation results in a mu nal Abandonment Notices shall be filed only afte	No. on file with BLM/BIA. Requi altiple completion or recompletion	The vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has						
07/26/06 Repaired down	nhole failure, per attached report.								
Prod. 08/01/06: 2 BO, 6	7 BW, 6 MCF								
			3-12395C						
			Neceived						
 I hereby certify that the foreg Name (Printed/Typed) 	oing is true and correct								
Celeste G. Dale	· · · · · · · · · · · · · · · · · · ·	Title Regulatory Spec	zialist						
Signature Juli	sti A. Ial	Date 10/04/06							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved by		Title	FOR RECUI						
Conditions of approval, if any, are a	attached. Approval of this notice does not warr or equitable title to those rights in the subject to conduct operations thereon.	ant or lease Office ACCE	EPTED BAR RECORD						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to makelbahy department or agener of the US States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. hited

	Sec.		Reg	ulatory S	ummar	y . : ;				
Conocol	Philips			SEMU ()38	9: 2 - 45 1				
REPAIR DOWNHOLE FAILURE, 7/21/2006 11:00										
API / UWI 300250625400	County LEA	1	Surf Loc Sec 24,T-20-S,R 37 E	N/S Dist (ft)	N/S Ref		E/W Dist (ft)	E/W Ref	Ĩ	Job Category WELL INTERVENTION
Ground Elevatior	n (ft)	Latitude (DMS) 0° 0' 0" N	Long 0° 0'	itude (DMS) 0" E		Spud D	oud Date 10/23/1951		Rig Release Date 11/25/1951	
7/21/2006 11:00 Last 24hr Summa	ary									
HELD PJSM. N PARTED ON B SHUT WELL IN	ODY. RIH AN	G UNIT. UNHANG ND LATCH ON FIS	WELL. BLED DN F H. UNSEAT PUMP	PSI INTO TRA . START COC	NS VAC TF DH WITH R	RUCK. ODS. F	COOH WITH F OUND SOME	RODS. P RODS P	ULLED ITTED.	83 3/4 C RODS, RO LAID DN 8 RODS.
7/24/2006 06:00) - 7/24/2006	17:30								
ND WELLHEAD JTS. RD SCAN	DPEN WELL. D, NU BOP. F INERS. TAG	RIH AND TFF. TO GED FILL @3913'	H WITH RODS. LA OK 115' TO TAG. M . WAIT ON REPLA 5 TUBING. SHUT W	IRU TUBING	SCANNER: ING. RIH V	s. coo	OH SCANNING	i 119 JTS	OF TU	BING FOUND 5 B
7/25/2006 06:00) - 7/25/2006	17:30								
WITH 15 BBLS	PEN WELL. TREATED 91	B DN TUBING. W	ICK. BLED DN PSI. /AIT 3 HRS. DISPL JT WELL IN, SION.	ACE 500 GAL	ND BOP, N 15 % ACID	IU WEL W/AD	LHEAD. DISF DITIVE FOLLO	PLACE 50 WD WIT	00 GAL H 20 BI	XYLENE FOLLOW
7/26/2006 06:00		14:00								· · · · · · · · · · · · · · · · · · ·
PROBLEMS GE	PEN WELL. TTING DN O PACE WELL	N 2ND SWAB RU	ALL BLOW. RIG U N. WAIT ON HOT (PTRUCK. LOAD AN	DILER. MIRU H	HOT OILER	. HOT	OIL TUBING A	ND FLO	WEINE	RIH WITH PUMP
<u>,</u>	· · · · ·									