Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

	DUDE LU CET LUE MAIS	** ***	_		l l	Esques. Maion 51, 5	007	
BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					1	5. Lease Serial No. LC030168A		
						6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If U	7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Gas Well Other						I Name and No.		
2. Name of Operator SOUTHWEST ROYALTIES, INC.						EAVES A #6		
3a Address 3b. Phone No. (include area code)						9. API Well No. 30-025-12005  10. Field and Pool, or Exploratory Area SCARBOROUGH; YATES 7 RIVERS  11. County or Parish, State		
6 DESTA DRIVE, STE 2100, MIDLAND, TX 79705 432/688-3267  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)								
UNIT D, 660' FNL & 660' FWL, SEC 19, T26S, R 37E								
					LE	A COUNTY, NM		
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE	NATURE	OF NO	TICE, REPORT,	OR OTHER DATA	i	
TYPE OF SUBMISSION			TYPE	OF ACT	TON			
Notice of Intent	Acidize Alter Casing	Deepen			ction (Start/Resume	·	Ŧ	
Subsequent Report	Casing Repair	Fracture T		Reclar		☐ Well Integrity ☐ Other		
Final Abandonment Notice	Change Plans	Plug and A	Abandon		orarily Abandon			
	Convert to Injection	Plug Back		Water	Disposal		· ·	
MI & RU WS. NU BOP. RIH w/tbg and tag CIBP s	or to commencing with P&A p et @ 3100' and cap w/25 sx cm ) sx cmt (300' - 200') and tag.							
RD PU; install dry hole marker; cover cellar and pit; clean location.  Prepare to rip & re-seed location and block any roads into well.  Schematic attached.						FOR FAPPPOV	Αv	
Schematic attached.					_		<b>AL</b>	
						12.23.24.25	2625	
4. I hereby certify that the foreg Name (Printed/Typed)	oing is true and correct					ラル	<del></del>	
DAWN M. HOW	ARD		Title OPE	RATION	S ASSISTANT			
Signature Dawon Howard			Date		10/19/2006	COIVE	Pag []	
)	THIS SPACE FOR F	EDERAL	OR STA	TE OF	FICE USE		- (N)	
pproved by			Title	Γ	ADD	DOVED.	-3	
onditions of approval, if any, are attentify that the applicant holds legal of hich would entitle the applicant to of	or equitable title to those rights in t	bes not warrant the subject leas	or —		AFF	A TOUC		
tle 18 U.S.C. Section 1001 and Title 4 ates any false, fictitious or frauduler	3 U.S.C. Section 1212, make it a cut statements or representations as	rime for any p to any matter v	erson knowi within its jur	ngly and v	rillfully to make).	any department or agenc	of the United	
Instructions on page 2)					ERENE	RICK WRIGHT		

GWW

FREDERICK WRIGHT PETROLEUM ENGINEER

# Eaves A #6 Yates 7 Rivers Lea, NM

API NO.:

30-025-12005

LEASE NO.

101791-006

### WELLBORE DIAGRAM

**ELEVATION** 


GL 2962'

KB

DF

#### Perferations:

3201-3283' Sqz. 3/12-15/50 w/50 sx. 3190-3200' in March 1950 3132-3179' in Aug. 1970 3121-3196' in June, 1981



9-7/8" HOLE TO 1179'

SURFACE CASING: 7-5/8" Set @ 1179' on 2-24-50 CEMENTED WITH 500 sx circ. to surface

6-3/4" HOLE to 3299'

Note: Report dated 5-23-97 shows Sub pump (FC 2200) on 2-7/8" set @ 3157.11'

TD:

3299'

Notice of intent dated 4/27/01 shows Prod. Equip. pulled from well & CIBP was set (or to be set) @ 3100'

Production Casing: 5-1/2" 14# J55 LT&C set @ 3299' Cemented back to surface w/780 sx on 3-5-50

#### **SUNDRY NOTICE SPECIAL STIPULATIONS**

- A. Approval is granted to P/A this well with the following modifications to the program:
- B. Tag the cement on top of the CIBP.
- C. Set a 25 sack cement plug @ 2740' for the base of the salt and tag.
- D. Set a 25 sack cement plug @ 1230' for the base of the intermediate casing shoe and the top of the salt and tag.
- E. The surface cement plug must be at least 25 sacks,

Engineering can be reached at 505-706-2779 for any variances that might be necessary.

F Wright 10/24/06